

LAND CORNER RECORDATION CERTIFICATE
FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF:-	LOCATED IN:-	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____	T. <u>40</u> N. <u>30</u> E. <u>W.</u>	<u>F1</u>
2. PROPERTY CONTROLLING IN SECTION <u>4</u>	T. <u>40</u> N. <u>30</u> E. <u>W.</u>	<u>5 & 5a</u>
3. MISCELLANEOUS PROPERTY IN SECTION _____	T. _____ N. _____ E. _____	_____
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Arthur O. Enger, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on see below, 19____, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Corner F1 (North 1/4 corner of Section 4, T40N, R30W):

Corner 5 (North 1/16 corner on N & S 1/4 line of Section 4, T40N, R30W):

Corner 5a (Southeast Corner of Lot 3, Section 4, T40N, R30W):

None of these corners established in original survey nor subsequently, apparently.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Corner F1: Established 6/13/75 proportionately on line between closing corner between Sec. 4 & 5 on 4th Correction Line 2637.7 ft. W and Standard Section Corner on 4th Correction Line between Sec. 35 & 36, T41N, R30W 933.2 ft. E.

Corner 5: Established 4/16/76 proportionately on line between Center 1/4 corner 1350.0 ft. S and N 1/4 corner 2155.3 ft. N.

Corner 5a: Established 4/16/76 proportionately on line between Center 1/4 corner 2700.5 ft. S and N 1/4 corner 805.3 ft. N.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner F1: 1" I.D. x 36" iron pipe with 3 1/2" aluminum cap.
Red Maple 6 N71°E (mag.) 28.5 ft. "1/4S, BT"
Red Maple 6 S60 1/2°E (mag.) 21.8 ft. "1/4S, BT"

Corner 5: 1" I.D. x 36" iron pipe with 3 3/4" aluminum cap.
Red Maple 10 S19°W (mag.) 17.5 ft. "1/16S, BT"
Red Maple 8 S31°E (mag.) 19.8 ft. "1/16S, BT"

Corner 5a: 1" I.D. x 36" iron pipe with 3 3/4" aluminum cap.
Sugar Maple 4 N89°W (mag.) 19.9 ft. "Lot 3, BT"
Red Maple 6 East (mag.) 47.1 ft. "Lot 2, BT"

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY Arthur O. Enger

MICHIGAN REGISTERED LAND SURVEYOR

Arthur O. Enger

Michigan Department of Natural Resources

13581

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

