LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

-		
.00	corners	: in

			1		
Dickinson	Located In:	Corner Code #			
(County) NAUCEDAH TOWNSHIP 1. Public Land Survey	- ТR ТR				
2. Property Controlling in Section	T R S 28 T 41N R 28 S T R S T R	W 04			
3. Miscellaneous Property in Sec.	S T R S T R		Register of I	Deeds Stamn	& File Number
4. Lot No. , Rec 5. Private Claims	corded Plat		A B C D	E F G	H I J K L 1
that under requirements of P.A. above were in conformance with	74, Michigan P.A. of 1970, the cregulations and rules therefore as	do hereby state orner points mentioned in lines 1 and 2 required in the current manual of survey	, 5	9-1-	-10 -11 -12
		u of Land Management or by a decree of		16-	-151413
	d of Land Surveyors or by a D	, 4 and 5 above were in conformance with Decree of a Court of Law; established,	9 19 20	21	-22 -23 -24
NOTE: Not more than 2 corn on this certificate.	ners, all in the same town and	range, may be recorded	10 30 29 11 12 31 32	33	27 26 25 34 35 36
A. Description of original m	onument and accessories an	nd/or subsequent restoration:	13		

- (04) Northwest One-Sixteenth corner of Section 28. Not set in original survey, no evidence of subsequent establishment.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (04) Corner position established at the intersection of the North and West One-Sixteenth lines of Section 28.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(04)DNR monument N39E 86.9' (1/16S,BT) 18" R. Pine 28.6' (1/16S,BT) 7" Aspen S16E 4" Spruce \$84W 41.81' (1/16S,BT) 4" Aspen N43W 18.61' (1/16S,BT) All trees are blazed, scribed, and painted. Measurements are to nail in side of tree, bearings are magnetic.

50447

PIPP SURVEYOR

July 22, 2013

Surveyor's Michigan License No.

Signed by