

✓

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 41. NR. 28. W.

----- Dickinson ----- COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 31 & 32 -----

DESCRIPTION OF CORNER MONUMENT 1" Pipe -----

WITNESSES TO CORNER 14" Hemlock - N 50 W - 62 Links -----

24" Hemlock - S 53 E - 76 Links -----

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

This corner was found by Forestry Division survey crew, while making a
partial resurvey of this Township. Corner had been previously located by unknown
Surveyor. One original B.T. still in place, in poor condition.

Corner was placed and witnessed July 20, 1954.

SURVEYORS SEAL

SIGNED Shaw C. Anderson DATE 2/11/55
REGISTERED LAND SURVEYOR