


MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION



LAND CORNER RECORD

T. 42 NR. 27 W.

Dickinson

COUNTY

DESCRIPTION OF CORNER 1/4 corner between sections 31 and 32

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER Cedar 10" N 18 E 20 links

Cedar 10" N 84 W 14 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR  
RESTORED.

Corner was replaced from original cedar bearings trees, one in fair condition and  
one in poor condition.

Corner was found while cruising timber in this area.

Corner was placed and witnessed on 7 February 1956

SURVEYORS SEAL

*Henry S. Peterson*

SIGNED Henry S. Peterson  
REGISTERED LAND SURVEYOR

DATE 2/8/56