LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

or corners in

| Dickinson | Located In: | Corner Code # | | | | |
|--|--|---|------------|-------------|--------------------|-------------|
| (County) ELCH TOWNSHIP . Public Land Survey | TR | | | | | |
| . Property Controlling 1 Section | T R S 30 T 42N R 28V S 30 T 42N R 28V S T R | | | | | |
| . Miscellaneous Property in Sec. | S T R R | | Regi | ster of Dee | eds Stamp & | File Number |
| . Lot No, Rec . Private Claims | | <u> </u> | 1 A B | C D E | F G H | I J K L M |
| Jeremy J. Pipp , in | | 2/2014 do hereby sta | ate 3 | | | ++++ |
| bove were in conformance with r structions of the United States \ensuremath{D} | regulations and rules therefore as i Department of the Interior, Bureau | orner points mentioned in lines 1 as required in the current manual of su of Land Management or by a decre 4 and 5 above were in conformance | e of 6 -10 | 17 | -1615 | -14-13- |
| | l of Land Surveyors or by a De | ecree of a Court of Law; establis | | 20 | -21 -22 | 23 24 |
| IOTE: Not more than 2 corn in this certificate. | ers, all in the same town and r | range, may be recorded | 10 30- | 32 | -28 -27 -33 -34 | 26 25 |

- . Description of original monument and accessories and/or subsequent restoration:
- (08) Center-West One-Sixteenth corner of Section 30. Not set in original survey. Found T Iron post East +/-16' from calculated position.
- (11) Southwest One-Sixteenth corner of Section 30. Not set in original survey, no evidence of subsequent establishment.
- 3. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (08) Corner position established at proportionate distance and on-line between the Center One-Quarter corner and the West One-Quarter corner of Section 30. Found T Iron not accepted.
- (11) Corner position established at the intersection of the South and West One-Sixteenth lines of Section 30.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

| (08) Dt | NR monument | (11) DNR monument |
|---------------|--------------------------|---|
| 4" Ironwood | N35E 33.36' (1/16S,BT) | 6" Twin Hemlock N77E 15.45' (1/16S,BT) |
| 12" Maple | S36E 41.55' (1/16S,BT) | 4" Ash S35E 14.11' (1/16S,BT) |
| 4" Maple | S44W 26.36' (1/16S,BT) | 5" Ash N88W 7.89' (1/16S,BT) |
| 9" Maple | N84W 21.14' (1/16S,BT) | 5" Maple N10W 19.57' (1/16S,BT) |
| All trees are | | All trees are blazed, scribed, and |
| painted. Meas | surements are to nail in | paint of manufements are to nail in single tree, dearings are magnetic. |
| side of tree, | bearings are magnetic | sing of tree treatings are magnetic. |

Surveyor's Michigan License No.

July 15, 2014

For the Michigan Department of Natural Resource

STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 Revised May 14, 1975

Revised Jan., 1983 Rervised Oct., 1995

20400

20401