

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

or corners in

Dickinson	Located In:	Corner Code #
(County)		
ELCH TOWNSHIP		
Public Land Survey	T R	
	T R	
	T R	
Property Controlling	S 30 T 42N R 28W	12
Section	S 30 T 42N R 28W	13
	S T R	
Miscellaneous	S T R	
Property in Sec.	S T R	

Lot No. , Recorded Plat
Private Claims

Jeremy J. Pipp, in a field survey on 7/02/2014 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
in this certificate.

u. Description of original monument and accessories and/or subsequent restoration:

(12) Center-South One-Sixteenth corner of Section 30. Not set in original survey, no evidence of
subsequent establishment.

(13) Southeast One-Sixteenth corner Section 30. Not set in original survey. 2013: Applekamp Land
Surveying (Steven Applekamp PS#43045) Set capped rebar at position.

3. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(12) Corner position established mid-point and on-line between the Center One-Quarter corner and
the South One-Quarter corner of Section 30.

(13) Accepted found Applekamp Monument. Position is accepted as a careful and faithful PERPETUATION
of the position of the original corner. Replaced monument with MDNR Aluminum Capped monument.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(12) DNR monument
6" Ash N53E 24.32' (1/16S,BT)
6" Ash S87E 27.78' (1/16S,BT)
6" Ash S06E 9.98' (1/16S,BT)
7" Tw. Ash N85W 15.42' (1/16S,BT)

All trees are blazed, scribed, and
painted. Measurements are to nail in
side of tree, bearings are magnetic

Signed by
Surveyor's Michigan License No. 50447

For the Michigan Department of Natural Resources

(13) DNR monument
10" Tamarack N25W 23.80' (1/16S,NBT)
EX 8" B. Spruce N29E 7.50' (- , -)
EX 7" B. Spruce N82E 9.73' (- , -)
8" B. Spruce S09E 30.98' (1/16S,NBT)
All trees are blazed, scribed, and
painted. Measurements are to nail in
side of tree, bearings are magnetic.



20402
20403