

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES  
LAND CORNER RECORD


Dickinson COUNTY  
T 42N R 28W

DESCRIPTION OF CORNER West 1/16 corner between Sections 5 and 8

CORNER MONUMENT 1" I.D. x 36" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED January 13, 1970

WITNESSES TO CORNER..... Cedar 7 N44°W (mag.) 41 lks. "1/16S, BT"



Cedar 6 N48°W (mag.) 45 lks. "1/16S, BT"

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Not established in original survey.

Found a 6' steel fence post and a 2" x 2" x 2' squared cedar post 16.4 lks. south and 9.7 lks. west of corner, but these were neither on line between nor equidistant from controlling corners to E and W.

Established the corner on line between section corner 1326.5 ft. west and 1/4 corner 1326.4 ft. east.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

Arthur O. Enger  
REGISTERED LAND SURVEYOR  
Arthur O. Enger

DATE December 21, 1971

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68