

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


Dickinson COUNTY
T 42 N R 28 W

DESCRIPTION OF CORNER North 1/16 corner between Sections 4 and 5

CORNER MONUMENT 1" I.D. x 36" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED March 26, 1970

WITNESSES TO CORNER..... Cedar 8 S82°E (mag.) 4.8 ft. "1/16S, BT"



Cedar 6 N 8°E (mag.) 8.8 ft. "1/16S, BT"

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Not established in original survey.

Found a 2" x 2" x 3 1/2" squared cedar post (no marks and no witnesses)
N78 1/2°E 8.3 ft. from corner position as calculated from measurements between
1/4 cor. to S and Sec. cor. to N.

Placed a new monument proportionately on line between 1/4 corner 1326.0 ft.
south and section corner 1362.2 ft. north.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

Arthur O. Enger
REGISTERED LAND SURVEYOR
Arthur O. Enger

DATE January 18, 1972

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68