

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Dickinson	Located In:	Corner Code #
(County)		
Fetch Township		
1. Public Land Survey	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S 14 T 42N R 29W	10
	S 14 T 42N R 29W	15
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Jeremy J. Pipp, in a field survey on 7/26/2012AD do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
Instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(10) South One-Sixteenth corner common to Sections 14 and 15. Not set in original  
survey, no evidence of subsequent establishment.

(15) West One-Sixteenth corner common to Sections 14 and 23. Not set in original  
survey, no evidence of subsequent establishment.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(10) Corner position established mid-point and on-line between the West One-Quarter  
corner and the Southwest corner of Section 14.

(15) Corner position established mid-point and on-line between the South One-Quarter  
corner and the Southwest corner of Section 14.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(10) DNR monument  
6" Aspen N48E 27.89' (1/16S,BT)  
7" Cherry S18E 7.49' (1/16S,BT)  
5" Ash S51W 29.83' (1/16S,BT)  
10" Balsam N24W 29.29' (1/16,NBT)  
All trees are blazed, scribed, painted,  
and signed. Measurements are to nail in  
side of tree, bearings are magnetic.

(15) DNR monument  
13" Maple N05W 23.02' (1/16S,BT)  
5" Aspen S52E 6.34' (1/16S,BT)  
10" Maple S59W 17.38' (1/16S,BT)  
7" Aspen N64W 12.75' (1/16,NBT)  
All trees are blazed, scribed, painted,  
and signed. Measurements are to nail in  
side of tree, bearings are magnetic.

Signed by Jeremy J. Pipp August 28, 2012  
Surveyor's Michigan License No. 50447

For the Michigan Department of Natural Resources, PROFESSIONAL SURVEYOR No. 50447

20095

20097



MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971  
Revised May 14, 1975  
Revised Jan., 1983  
Revised Oct., 1995