

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Dickinson	Located In:	Corner Code #
(County)		
Felch Township		
1. Public Land Survey	T 42N R 29W	L05
	T	R
	T	R
	T	R
2. Property Controlling in Section	S T R	
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No.	Recorded Plat	
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Jeremy J. Pipp, in a field survey on 7/30/2012AD do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(L05) Quarter corner common to Sections 12 and 13. 1849: John Burt,DS. Hemlock 16 Quarter Section Corner.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(L05) No evidence of original survey or subsequent restoration found. Corner position reestablished by single proportionate measurement between the Southwest corner and the Southeast corner of Section 13; Hemlock remains in area, but no definate evidence. Position checks well with line calls East & West ("37.00 Chains - Top of knob of greenstone"), ("45.00 Chains - Foot of hill & enter swamp"), ("45.50 Chains - Brook 5L C. South"), ("61.00 Chains - Ledge 10 Links South of Line 30 Feet" \*\*NOTE: Drill holes in outcrop, ledge position altered\*\*). Position is accepted as a careful and faithful REESTABLISHMENT of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(L05) DNR monument  
7" Spruce S52E 17.44' (1/4S,NBT)  
6" Maple S76W 10.95' (1/4S,NBT)  
6" Maple N73W 32.18' (1/4S,NBT)  
9" White Birch N42W 21.43' (1/4S,NBT)  
All trees are blazed, scribed, painted, and signed. Measurements are to nail in side of tree, bearings are magnetic. A carsonite rail was set North 1.5 feet.

Signed by Jeremy J. Pipp  
Surveyor's Michigan License No. 50447



August 28, 2012

For the Michigan Department of Natural Resources, Office of Land and Facilities