## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

I

For corners in

Dickinson	_ Located In:	Corner Code #								
(County) FELCH TOWNSHIP 1. Public Land Survey	TR TR									
2. Property Controlling in Section	S 7 T 42N R 29W S 7 T 42N R 29W S T R	06 10								
3. Miscellaneous Property in Sec.	S T R R		F	Regist	er of D	eeds S	tamp &	File Nu	mber	
4. Lot No. , Recorded Plat  5. Private Claims  ABCDEFGHIJKLE							м			
J. PHVALE CLAIMS	2/25/201	3AD	2	6-	_ <u> </u> _ 5					_
, Jeremy J. Pipp , in a field survey on 2/20/2013		3AD do hereby state	3	•			1	+-	++	_
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2										
shove were in conformance with regulations and rules therefore as required in the current manual of survey nstructions of the United States Department of the Interior, Bureau of Land Management or by a decree of 6 18 17 16 15 14 13								4		
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7 the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, 8 19 20 21 22 23 24							++	+		
re-established, monumented, recovered, found as expressed below:					-20-		22	123	11	_

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
- (06) Northeast One-Sixteenth corner of Section 7. Not set in original survey, no evidence of subsequent establishment.
- (14) South One-Sixteenth corner common to Sections 12 and 7. Not set in original survey. 1960: Kimberly Clark (Neal Sperhake PS#7876) Set 1" pipe with 4" Brass cap witnessed by Maple 4 S88E 34 links (22.44'), Elm 8 N64W 41 links (27.06')
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (06) Corner position established at the intersection of the North and East One-Sixteenth lines of Section 7.
- (10) Accepted found Kimberly Clark Monument and remains of One existing NBT Witness. Left Kimberly Clark Monument in place and rewitnessed.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(06)	DNR monument	(10) Kimberly Clark monument
10" ASH	NO9E 42.14' (1/16S,BT)	5" ASH N30E 52.95'(1/16S,NBT)
8" Maple	EAST 15.09' (1/16S,BT)	EX. 12" Maple \$81E 22.14' ( - , - )
11" Maple	\$43W 13.35' (1/16S,BT)	8" ASH S28W 37.88'(1/16S,NBT)
11" Maple	N24W 26.61' (1/16S,BT)	6" ASH N74W 16.92'(1/16S,NBT)
All trees a	re blazed, scribed, and	All trees are blazed, scribed, and
painted. M	leasurements are to nail in	pain and Measurements are to nail in
side of tre	e, bearings are magnetic.	pain ador messaments are to nail in side of tree, bearings are magnetic.

Surveyor's Michigan License No.

July 22, 2013

For the Michigan Department of Natural Resource

20182 20177

Signed by