also T42N-R30W M05 also T42N-R30W M06

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Dickinson	Located In:	Corner Code #	
(County) FELCH TOWNSHIP			
Public Land Survey	T 42N R 29W T 42N R 29W T R		
2. Property Controlling in Section	S T R S T R		
3. Miscellaneous Property in Sec.	S T R		
4. Lot No. Rec	corded Plat		Register of Deeds Stamp & File Number
5. Private Claims			ABCDEFGHIJKLM
	2/20/2	013AD	2 - 5 1 - 1 - 1 - 1 - 1
, Jeremy J. Pipp , ir	n a field survey on 2/20/2	013AD do hereby state	3
		er points mentioned in lines 1 and 2	4 - 7 9 9 10 12 12 12 12
above were in conformance with r	egulations and rules therefore as rec	uired in the current manual of survey	y 5
	Department of the Interior, Bureau of		
		and 5 above were in conformance with	
	i of Land Surveyors or by a Decr	, 8 -19 -20 -21 -22 -23 -24	
'e-established, monumented, recove	ered, found as expressed below:		9
NOTE: Not many than 2 area	and all to the annual to the		10 30 29 28 27 26 25
	ners, all in the same town and ra	11	
on this certificate.			12-31-32-33-34-35-36-
			13

A. Description of original monument and accessories and/or subsequent restoration:

(AO5) Corner common to Sections 12, 13, 7, and 18. 1846: John & Austin Burt, DS. B. Ash post witnessed by: Fir 8 N10E 4 links (2.64'); Spruce 12 S44W 9 links (5.94'); 1960: Kimberly Clark (Neal Sperhake PS#7876) Set 1" pipe with 4" Brass cap witnessed by Maple 8 N50W 77 links (50.82'), Elm 4 N76W 7 links (4.62'), B. Ash 4 S30W 46 links (30.36'), Poplar 11 \$74E 35 links (23.10').

(A06) Quarter corner common to Sections 13 and 18. 1846: John & Austin Burt, DS. Set Cedar post witnessed by: Cedar 6 S77E 23 links (15.18'); Cedar 8 N17W 13 links (8.58'); 1960: Kimberly Clark (Neal Sperhake PS#7876) Set 1" pipe with 4" Brass cap witnessed by Cedar 12 S10W 41 links (27.06'), Cedar 9 S28E 41 links (27.06').

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(A05) Kimberly Clark Monument not found, only the NE Maple NBT were recovered. Remonumented the corner postion with a Michigan DNR Monument using the record distance from the existing NBT where it intersects the proportionate distance between 1/16 corner North and Quarter Corner South. Position checks within reason to Quarter corner East. Accepted position to be a careful and faithful REESTABLISHMENT of the position of the original corner.

(A06) Accepted found Kimberly Clark Monument and remains of Two existing NBT Witnesses. Left Kimberly Clark Monument in place and rewitnessed. Accepted found Kimberly Clark Monument and Witness remains as a careful and faithful PERPETUATION of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(A05) DNR	monument		(A06)	Kimberly Clark monument		
EX. 13" Maple	N57E 50.82'	(- , -)	3" ASH	S80E 27.52' (1/4S,NBT)		
9" Cedar	S10E 44.21'	(S18,NBT)	3" ELM	\$13E 27.66' (1/4S,NBT)		
8" ASH	\$35W 41.11'	(S13,NBT)	10" Spruce	S64W 12.18' (1/4S,NBT)		
8" Maple	N31W 4.78'	(S12,NBT)	11" Maple	N54W 6.64' (1/4S,NBT)		
All trees are blazed, scribed, and			All trees are blazed, scribed, and			
painted. Measurements are to nail in			painted Measurements are to nail in			
side of tree, bearings are magnetic. A_			side & Ple	Chearings are magnetic. A		
Carsonite rail was set North 1.5 feet			Carsonite ra	ail was set North 1.5 feet.		
Signed by	(Joses	- Jan Je	JERE	MYDate July 22, 2013		

Surveyor's Michigan License No. /

PIPP

OFERRION

PROFESSIONA est Respunçativi Ao For the Michigan Department of Natural Resource

20176 20175 FORM APPROVED BY MICHIG TE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 Revised May 14, 1975