

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

or corners in

| | | |
|-------------------------|------------------|---------------|
| Dickinson | Located In: | Corner Code # |
| (County) | | |
| ELCH TOWNSHIP | | |
| Public Land Survey | T 42N R 29W | J10 |
| | T R | |
| | T R | |
| Property Controlling | S T R | |
| Section | S 24 T 42N R 29W | 09 |
| | S T R | |
| Miscellaneous | S T R | |
| Property in Sec. | S T R | |
| Lot No. , Recorded Plat | | |
| Private Claims | | |

6/26/2014
7/01/2014
Jeremy J. Pipp, in a field survey on do hereby state
at under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
structions of the United States Department of the Interior, Bureau of Land Management or by a decree of
Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
e rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
established, monumented, recovered, found as expressed below:

OTE: Not more than 2 corners, all in the same town and range, may be recorded
n this certificate.

Description of original monument and accessories and/or subsequent restoration:

J10) Center One-Quarter Corner of Section 26. Not set in original survey, no evidence of
ubsequent establishment.

09) Center-East One-Sixteenth corner of Section 24. Not set in original survey, no evidence of
ubsequent establishment.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

J10) Corner position established at the intersection of the North-South and East-West One-Quarter
lines of Section 26.

09) Corner position established mid-point and on-line between the Center One-Quarter corner and
the East One-Quarter corner of Section 24. Monument set on rock outcrop in karn of stones.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(J10) DNR monument
18" Tw. Maple N38E 20.45' (1/4S,BT)
12" Maple S56E 18.42' (1/4S,BT)
3" Ash S12W 21.38' (1/4S,BT)
3" Maple N47W 11.38' (1/4S,BT)

All trees are blazed, scribed, and
painted. Measurements are to nail in
side of tree, bearings are magnetic.

signed by
Surveyor's Michigan License No. 50447

For the Michigan Department of Natural Resources Forest Resource Division

(09) DNR monument
3" Maple N29E 17.37' (1/16S,BT)
3" Maple S39E 17.95' (1/16S,BT)
7" Maple S79W 5.47' (1/16S,BT)
4" Maple N02W 16.50' (1/16S,BT)

All trees are in clumps of same species.
All trees are blazed, scribed, and
painted. Measurements are to nail in
side of tree, bearings are magnetic.

