

# LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

(DICKINSON COUNTY)

FOR CORNERS OF:-	LOCATED IN:-	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____ T. _____ N. S., R. _____ E. W.		
2. PROPERTY CONTROLLING IN SECTION <u>21</u> , T. <u>42</u> N. <u>8</u> , R. <u>29</u> E. W.		#15 & #16
3. MISCELLANEOUS PROPERTY IN SECTION _____ , T. _____ N. S., R. _____ E. W.		
4. LOT NO. _____ , RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Arthur O. Enger, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on see below, 19\_\_\_\_, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_, 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Corner 15 (West 1/16 corner between Sections 21 & 28, T42N, R29W):

Corner 16 (East 1/16 corner between Sections 21 & 28, T42N, R29W):

Neither of these corners established in original survey nor subsequently, apparently.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Corner 15: Established 5/4/77 on line between Sec. Cor. 20.083 ch. W and 1/4 cor. 20.083 ch. E.

Corner 16: Established 5/9/77 on line between Sec. Cor. 19.972 ch. E and 1/4 cor. 19.972 ch. W.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner 15: 1" I.D. x 36" iron pipe with 3 1/2" aluminum cap.  
Y. Birch 13 N64°E (mag.) 2.8 ft. "1/16S, BT"  
⊕ chiselled in vertical rock ledge S41°W (mag.) 5.4 ft.

Corner 16: 1" I.D. x 36" iron pipe with 3 3/4" aluminum cap.  
Sugar Maple 4 N44°W (mag.) 20.7 ft. "1/16S, BT"  
Cedar 15 N52°E (mag.) 42.8 ft. "1/16S, BT"  
Declination is 1°45' West

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_

(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

APPROVED AND SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

CHIEF OF SURVEY PARTY

MICHIGAN REGISTERED LAND SURVEYOR

Arthur O. Enger

Michigan Department of Natural Resources

SURVEYOR'S MICHIGAN REGISTRATION NO. 13581

