

**LAND CORNER RECORDATION CERTIFICATE**  
**Filing Requirement of Act 74, Mich. P.A. 1970**

For corners in

Dickinson  
(County)

Located In:

Corner Code ##

1. Public Land Survey

T 43N R 27W  
T 43N R 27W

E-11  
D-11

2. Property Controlling  
in Section

S      T      R       
S      T      R     

3. Miscellaneous  
Property in Sec.

S      T      R       
S      T      R     

Register of Deeds Stamp & File Number

4. Lot No.         , Recorded Plat         

5. Private Claims         

I, David B. Babbitt, in a field survey on 6/27/86, 19 86

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE:** Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

E-11 NW section corner of Section 33.

Cedar Post.  
Cedar 16 - S42E - 25Lks.  
Cedar 16 - N73E - 12Lks.

D-11 N1/4 corner of Section 32

Cedar Post.  
Hemlock 12 - S57E - 25Lks.  
Cedar 18 - N53W - 28Lks.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E-11 Set by double proportion to the G.L.O. record using section corners 1 mile east and 2 miles west and 1/4 cors. 1/2 mile north & 1/2 mile south. Could not identify OBT's.

D-11 Set MPOL between the NW and NE section corners of Section 32. Corner falls in E-W blacktop road.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-11 D.N.R. Monument

12" cedar N47W - 47.9'  
10" cedar N23E - 42.2'  
10" cedar S30E - 79.3'  
7" cedar S21E - 82.9'  
E BLACKTOP ROAD - South 16.5'

D-11 1" pipe with plastic RLS cap.

6" cedar S32W - 57.2'  
10" w. spruce S26E - 66.5'  
8" w. spruce N58E - 58.1'  
6" b. spruce N08W - 27.1'

Signed by

David B. Babbitt

Date

6-9-86

Surveyor's Michigan License No.

21558