

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

43N 26 W
T 43 NR 27 W

Dickinson

COUNTY

DESCRIPTION OF CORNER Section corner common to sections 7 and 18, T43N R26W and sections 12 and 13, T43N R27W.

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap, marked 6" black spruce growing very close to corner. Scribed section number on squared face.

WITNESSES TO CORNER

Black spruce 6" N 24 W 33 links, marked S 12 NBT

Cedar 5" S 71 E 31 links, marked S 18 NBT

Black spruce 5" S 51 W, 12 links, marked S 13 NBT


DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from two original tamarack bearing trees, one in good condition and one in fair condition. Scribe marks very plain on both.

Corner was found while cruising timber in this area.

Corner was placed and witnessed on 30 November 1956 with J. Doyle Voice.

SURVEYORS SEAL


SIGNED Henry S. Peterson
REGISTERED LAND SURVEYOR

DATE 12/6/56