

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T<sup>43</sup> NR 27 W

Dickinson COUNTY

DESCRIPTION OF CORNER Section corner common to sections 14, 15, 22 and 23

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER Cedar 12" S 67 E 27 links, marked S 23 NBT

Cedar 8 " S 43 W 26 links, marked S 22 NBT

Distances measured from center of brass cap to NBT notch

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR  
RESTORED.

This corner was replaced from two original hard maple bearing trees. Both down. One with BT and description blazes plainly evident in overgrowth. No identifying marks visible on other but in proper position. Wood post in place. Measurements check west to swamp edge 1 chain (edge indistinct) and 3.30 chains North to swamp edge. This edge clearly defined.

Corner was found while cruising timber in this area.

Corner was placed and witnessed on 9 July 1957 with Norman J. Karsten.

SURVEYORS SEAL

*Henry S. Peterson*  
SIGNED Henry S. Peterson DATE 7/11/57  
REGISTERED LAND SURVEYOR