

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 N.R. 28

Dickinson


COUNTY

DESCRIPTION OF CORNER Section Corner for Sections ^{29/28} 32/33

CORNER MONUMENT 1" Iron pipe with 1/4" Aluminum Cap. Pipe inserted in 1-1/4" pipe.

DATE MONUMENT PLACED AND WITNESSED 12-21-62

WITNESSES TO CORNER..... NBT's: 12" W. Pine (S 28)(NBT) N 24° E 3 1/4 links



9" W. Pine (S 33)(NBT) S 50° E 76 1/2 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner was replaced from 1-1/4" iron pipe / blazed pine stumps in vicinity

No original evidence found.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 8-22-63
REGISTERED LAND SURVEYOR
Billy D. Buckler