

MAY 07 1997

COMMISSIONER

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

1996 SEP 11 PM 2:30

For corners in  
Dickinson  
(County)

Located In:

Corner Code #

REGISTER OF DEEDS  
DICKINSON COUNTY  
RON MOORE, CLERK

- |                                      |             |     |
|--------------------------------------|-------------|-----|
| 1. Public Land Survey                | T 43N R 30W | D-1 |
|                                      | T 43N R 30W | C-1 |
|                                      | T R         |     |
|                                      | T R         |     |
| 2. Property Controlling in Section   | S T R       |     |
|                                      | S T R       |     |
| 3. Miscellaneous Property in Section | S T R       |     |
|                                      | S T R       |     |

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, James H. Moore, in a field survey on May 30, 19 96, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

D-1 North 1/4 Section 5  
Cedar Post by John Burt 1846  
Original Bearing Trees  
Cedar 14" N64E 32 LKS  
Cedar 10" N57W 33 LKS

C-1 North West Corner Section 5  
Spruce Post by John Burt 1846  
Original Bearing Trees  
Spruce 3" N38E 44 LKS  
Tamar 5" N75W 146 LKS

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

D-1 No evidence of Original Corner or Accessories Remain  
Found 1 1/2" O.D. Pipe projecting about 8"

C-1 No evidence of Original Corner or Accessories Remain  
Found 1 3/8" O.D. Pipe projecting about 6"  
Corner previously recorded by Thomas O'Brien, P.S. 21274, March 4, 1977

ACCEPTED BY THE DICKINSON COUNTY  
SURVEY PEER GROUP AS THE OFFICIAL  
CORNER UNDER MICHIGAN PUBLIC ACT  
345 OF 1990 AT A MEETING HELD ON  
9-9-96  
RFP  
COUNTY REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D-1 Accepted above described Corner  
Replaced 1 1/2" O.D. Pipe with 2 1/2" stamped D.C.  
Remon. Corner  
New Witnesses  
Carsonite Stake South 3.0'  
Balsam 6" N38W 24.03'  
Balsam 5" N47E 18.15'  
Cedar 6" S70E 21.37'  
Cedar 4" S54W 8.63'

C-1 Accepted above described Corner  
Replaced 1 3/8" O.D. Pipe with 2 1/2" stamped  
D.C. Remon. Corner  
New Witnesses  
Carsonite Stake South 2.0'  
Tamarack 3" N37W 77.87'  
Tamarack 3" N8W 50.47'  
Tamarack 4" S62W 55.10'  
Tamarack 3" S68E 19.15'

Signed by

Date July 2, 1996

Surveyor's Michigan License 28423

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN., 1983

