

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T 43 NR 30 W

Dickinson

COUNTY

DESCRIPTION OF CORNER 1/4 corner between sections 19 and 20

DESCRIPTION OF CORNER MONUMENT 1" iron pipe with 4" brass cap.

WITNESSES TO CORNER 18" cedar stump S 70 W 10 links marked 1/4 S NBT

11" cedar N 50 W 30 1/2 links marked 1/4 S NBT

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

This corner was replaced from one original bearing tree in excellent condition
(Cedar 12 N78W 17) and one in place but in poor condition (cedar 10 S76 E 8)
Wood post in place in fence line.

Corner was found by Clarence Ryberg and Toivo Kauma, Forestry Division Personnel
while cruising timber in this area on 9 November 1960.

Corner was placed and witnessed on 16 December 1960

SURVEYORS SEAL



Henry S. Peterson

SIGNED

REGISTERED LAND SURVEYOR

12/19/60

DATE