

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Dickinson	Located In:	Corner Code #
(County)		
WEST BRANCH TOWNSHIP		
1. Public Land Survey	T 44N R 27W	B09
	T 44N R 27W	D07
	T R	
2. Property Controlling in Section	S T R	
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

9/25/2013AD
9/24/2013AD
do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(B09) Quarter corner common to Sections 19 and 30. 1850: John Burt, DS. Cedar 10 for quarter section corner witnessed by Spruce 14 S69E 31 links (20.46'). 1984: Michigan DNR (David Babbitt PS#21558) Set 1" pipe with 4" Aluminum cap witnessed by 11" W. Spruce S87E 107.1', 6" W. Spruce N30E 47.7', 9" W. Spruce N21W 37.5', 8" W. Spruce S85W 94.8'.

(D07) Quarter corner common to Sections 17 and 20. 1850: John Burt, DS. Set Cedar quarter section corner post witnessed by Cedar 14 N17E 35 links (23.10'), Spruce 14 S10W 27 links (17.82'). 1963: Michigan DNR (Billy Buckler PS#8887) Set 1" pipe with 4" Aluminum cap witnessed by 8" Cedar S57W 31 links (20.46'), 8" Cedar S56E 28 1/2 links (18.81').

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(B09) Accepted found MDNR Monument and four existing NBT Witnesses (two living, two dead). Position is accepted as a careful and faithful REESTABLISHMENT of the position of the original corner.

(D07) Accepted found MDNR Monument and Two existing NBT's as a careful and faithful PERPETUATION of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(B09) DNR monument
EX 9" Spruce N30E 47.84' (- , -)
6" Tw. Spruce S44E 12.91' (1/4S,NBT)
7" Spruce S80W 41.30' (1/4S,NBT)
EX 15" Spruce N21W 37.83' (- , -)

All trees are blazed, scribed, painted, and signed. Measurements are to nail in side of tree, bearings are magnetic. A Carsonite post was set North 1.5 feet.

Signed by
Surveyor's Michigan License No. 50447

(D07) DNR monument
8" Cedar N79E 8.39' (1/4S,NBT)
EX 10" Cedar S58E 10.80' (- , -)
EX 10" Cedar S63W 21.45' (- , -)
14" Cedar N03E 13.85' (1/4S,NBT)

All trees are blazed, scribed, painted, and signed. Measurements are to nail in side of tree, bearings are magnetic. A Carsonite rail was set North 1.5 feet.

Signed by JEREMY PIPP
Date October 1, 2013
PROFESSIONAL SURVEYOR

For the Michigan Department of Natural Resources, Forest Resources Division

20303

20299

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
Revised May 14, 1975
Revised Jan., 1983
Revised Oct., 1995