

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 44. NR. 27. E.
T. 44. N. R. 28. W.

----- Dickinson ----- COUNTY

DESCRIPTION OF CORNER ~~Section Corner common to Sections 19, 20, 24, 25~~ -----

DESCRIPTION OF CORNER MONUMENT ~~1" Pipe with 4" Brass cap~~ -----

WITNESSES TO CORNER ~~12" Cedar - N 45 W - 223 Links~~ -----

~~12" Spruce - N 1 E - 305 Links~~ -----

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

This corner was found by Forestry Division survey crew, while making
a partial resurvey of this area. One original B.T. still in place, down, but in
good condition.

Corner marker is placed 83 Links North of where it belongs. Bank erosion from
river would place true corner in the river. Corner is on North Bank of river.

Corner placed and witnessed March 12, 1952.

SURVEYORS SEAL

SIGNED

Lawrence C. DeMeyer
REGISTERED LAND SURVEYOR

DATE 7/8/52