

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T.44.. NR. 27.. W

.. D i c k i n s o n .. COUNTY

DESCRIPTION OF CORNER .. Section corner common to Sections 11, 12, 13, 14 ..

DESCRIPTION OF CORNER MONUMENT .. 1" Pipe with 4" Brass Cap.

WITNESSES TO CORNER 14" W. Pine .. (S 14 NBT) .. S 56° W .. 21 Links ..

No others available.

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED. This corner was replaced from one W. Pine B. T. (down) and badly rotted.
Bearing N 37° E 47 Links. Found several scribe marks and overgrowth.

Corner was placed and witnessed August 18, 1959 with H. S. Peterson, District
Forester.

SURVEYORS SEAL

SIGNED Billy D. Buckler .. DATE 4/29/60 ..
REGISTERED LAND SURVEYOR
Billy D. Buckler