

OK B. Babbitt

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Dickinson  
(County)

Located In: Corner Code ~~##~~

1. Public Land Survey T 44N R 27W A-3, B-1, A-2.  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_

2. Property Controlling S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
in Section S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

3. Miscellaneous S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
Property in Sec. S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

I, David Babbitt, in a field survey on 8/4/87, 19\_\_\_\_\_, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

- A-3. Southwest section corner of Section 6. Sugar post. Sugar 16, S77W, 25 Lks.  
DO 12, N22E, 35 Lks.  
DO 16, S52E, 30 Lks.  
Y.Birch 12, N35W, 45 Lks.
- B-1. North 1/4 corner of Section 6. Mich. Dept. of Conservation (Billy Buckler) 4-13-1964.  
One 1/2"x12" re-rod buried 1 ft. below ground level and another the same size at ground level in south wheel track of woods road. 9" elm, N10E, 15 1/2 Lks., 12" elm, N79E, 41 1/2 Lks.  
12" basswood, S21W, 32 Lks.
- A-2. West 1/4 corner of Section 6. Sugar post. Sugar 14, S75E, 28 Lks.  
DO 12, N52W, 20 Lks.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- A-3. Set by single proportion to the GLO record using the section corner 2 miles south and the twp. corner 1 mile north.
- B-1. Found 1/2" re-rod buried in south wheel track of woods road. Both elm NBT's were dead and had been cut but the stumps are still in place. The basswood NBT is partially dead but still standing.
- A-2. Set by single proportion to the GLO record using the section corner 2 1/2 miles south and the twp. corner 1/2 mile north.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- |                             |   |                             |
|-----------------------------|---|-----------------------------|
| A-3. DNR Monument           | B-1. 1/2" rerod buried in s. wheel track of trail road. | A-2. DNR Monument           |
| 6" sugar maple, N1E, 34.75' |   | 4" sugar maple S40E, 29.7'  |
| 5" sugar maple S50E, 27.8'  | 6" aspen, N43W, 50.3'                                   | 10" w.birch, S46W, 17.0'    |
| 10" sugar maple S22W, 15.2' | 9" maple, S40W, 59.5'                                   | 6" sugar maple, N53W, 12.3' |
| 6" sugar maple, N77W, 11.2' | 7" maple, S14E, 48.1'                                   | 6" spruce, N1E, 42.1'       |
|                             | 4" bl.ash, N54E, 19.0'                                  |                             |

Signed by David B. Babbitt Date 12-3-87

Surveyor's Michigan License No. 21558