

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--:	LOCATED IN--:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____	T. <u>44</u> ^{N.} XX , R. <u>29</u> XX ^{W.}	<u>H3</u>
2. PROPERTY CONTROLLING IN SECTION <u>3</u>	T. <u>44</u> ^{N.} XX , R. <u>29</u> XX ^{W.}	<u>16</u>
3. MISCELLANEOUS PROPERTY IN SECTION _____	T. _____ ^{N.} XX , R. _____ ^{E.} XX ^{W.}	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Arthur O. Enger, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on September 22, 1975, ~~19~~ established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Corner H3 (1/4 corner between Sections 3 & 10, T44N, R29W):

Cedar Post (Not found. No subsequent monuments found.)
Tamarack 7 N34W 13 (" " " " " ")
Spruce 9 S 3W 10 (" " " " " ")

Corner 16 (East 1/16 corner between Sections 3 & 10, T44N, R29W):

Not established in original survey nor subsequently, apparently.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Corner H3: Established on line between Sec. Cor. S89°49'W 39.789 ch. and Sec. Cor. N89°49'E 39.789 ch.

Corner 16: Established on line between 1/4 cor. 19.890 ch. W and Sec. Cor. 19.889 ch. E.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner H3: 1" I.D. x 36" iron pipe with 3 3/4" aluminum cap.

Cedar 16 N46°W (mag.) 16.2 ft. "1/4S, NBT"

Cedar 18 N88°E (mag.) 62.0 ft. "1/4S, NBT"

Corner 16: 1" I.D. x 36" iron pipe with 3 3/4" aluminum cap.

Cedar 12 S58°E (mag.) 10.0 ft. "1/16S, BT"

Cedar 10 N25°W (mag.) 35.8 ft. "1/16S, BT"

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY Carl R. Johnson DATE January 21, 1976

Carl R. Johnson CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY Arthur O. Enger DATE January 21, 1976

MICHIGAN REGISTERED LAND SURVEYOR

Arthur O. Enger

Michigan Department of Natural Resources

SURVEYOR'S MICHIGAN REGISTRATION NO. 13581