

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 44 N.R. 29 W


Dickinson COUNTY

DESCRIPTION OF CORNER Section Corner for Sections 20, 21, 28, 29

CORNER MONUMENT 1" Iron Pipe with 4" Brass Cap

DATE MONUMENT PLACED AND WITNESSED 9/15/60

WITNESSES TO CORNER..... 12" Spruce (S 20 NBT) N 09° W 25 Links



6" Spruce (S 29 NBT) S 66° W 27 Links

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-established from 1/4 corner to North; Section Corner to South;

Swamp edges to South, West and East check fairly well. Old blazes in vicinity.

SURVEYOR'S SEAL

SIGNED

*Billy D. Buckler*

REGISTERED LAND SURVEYOR

Billy D. Buckler

DATE 2/21/61