

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Dickinson Located In: Corner Code #
Sagola Township
1. Public Land Survey
2. Property Controlling in Section
3. Miscellaneous Property in Sec.
4. Lot No. Recorded Plat
5. Private Claims

Register of Deeds Stamp & File Number

Table with 13 rows and 13 columns (A-M). Contains numbers 1-36 and a small diagram of a corner point.

I, Jeremy J. Pipp, in a field survey on 5/09/2012AD do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(14) South One-Sixteenth corner common to Sections 23 and 24. Not set in original survey. 1963 Michigan DNR (Billy Buckler PS#8887) Set 1" Pipe capped with 4" Alum. cap MDNR Monument witnessed by, 7" W. Birch N71W 28 links (18.48'), 4" Spruce N33E 08 1/2 links (5.61'); other BT's not of record facing corner position.

(16) East One-Sixteenth corner common to Sections 23 and 26. Not set in original survey. 1963 Michigan DNR (Billy Buckler PS#8887) Set 1" Pipe capped with 4" Alum. cap MDNR Monument witnessed by, 6" Spruce N47E 37 links (24.42'), 5" Tw. S. Maple S49W 56 links (36.96').

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(14) Accepted found MDNR Monument and remains of existing Witnesses (NE mound, NW dead stub). Left MDNR monument in place and witnessed.

(16) Accepted found MDNR Monument and Two existing Witnesses. Left MDNR monument in place and witnessed.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(14) DNR monument
15" Spruce N41E 54.95' (1/16S,NBT)
EX. 7" Cedar S22E 18.43' (-,BT)
10" Cedar S21W 30.01' (1/16S,NBT)
15" Spruce N09W 28.12' (1/16S,NBT)
All trees are blazed, scribed, and painted. Measurements are to nail in side of tree, bearings are magnetic.

(16) DNR monument
EX. 11" Spruce N49E 24.84' (1/16S,BT)
11" Spruce N87E 29.18' (1/16S,NBT)
EX. 9" Maple S53W 37.29' (1/16S,BT)
11" Spruce N78W 47.05' (1/16S,NBT)
All trees are blazed, scribed, and painted. Measurements are to nail in bearings are magnetic.

Signed by Jeremy J. Pipp Surveyor's Michigan License No. 50447 Date July 18, 2012