

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Dickinson Located In: Corner Code #
Sagola Township
1. Public Land Survey T 44N R 30W K08
2. Property Controlling in Section S T R
3. Miscellaneous Property in Sec. S T R
4. Lot No. Recorded Plat
5. Private Claims

Register of Deeds Stamp & File Number

Table with 13 rows and 13 columns (A-M). Contains numbers 1-36 in a grid pattern.

I, Jeremy J. Pipp, in a field survey on 5/09/2012AD do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(K08) Quarter Corner common to Sections 23 and 24. 1848: John Burt, DS. Set Cedar post witnessed by: Cedar 10 S36E 3 links (1.98'); Cedar 12 N14W 16 links (10.56'); 1963: Michigan DNR (Billy Buckler PS#8887) Set 1"pipe with a 4" aluminum cap witnessed by 3" S. Maple S27E 10 links (6.60'), 9" W. Birch N52E 25 Links (16.50'); 1995: Edward Kazianka PS#14765 Found 1"pipe with a 4" brass cap & witnessed it with 6" Maple S27E 6.95', 12" Maple S39W 47.80', 6" Maple N66W 8.75', 10" W Birch S59E 13.15'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(K08) Accepted found MDNR Monument and existing Witnesses as a careful and faithful REESTABLISHMENT of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(K08) DNR monument
7" Maple N52E 31.40' (1/4S,NBT)
EX. 10" Maple S24E 7.05' (-, -)
EX. 12" Maple S42W 47.86' (-, -)
EX. 8" Maple N64W 8.75' (-, -)
All trees are blazed, scribed, painted, and signed. Measurements are to nail in side of tree, bearings are magnetic, carsonite rail was set North 1.5 feet.



Signed by [Signature] Date July 18, 2012
Surveyor's Michigan License No. 50447