

JAN 11 2001

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

FILED

Copy

00 AUG 22 PM 2:45

**LINDA M. TWITCHELL
REGISTER OF DEEDS
EATON COUNTY, MICH.**

For Corners in EATON Located In: Corner Code #
(county)

1. Public Land Survey T 2N R 6W A-6
WEST 1/4 CORNER T R
SECTION 18, T R
KALAMO TOWNSHIP, T R
ON RANGE LINE

2. Property Controlling S T R
in Section S T R

3. Miscellaneous S T R

4. Lot No _____, Recorded Plat _____

5. Private Claims _____

LIBER

PAGE 147

Register of Deeds Stamp & File Number

| | A | B | C | D | E | F | G | H | I | J | K | L | M |
|----|----|----|----|----|----|----|---|---|---|---|---|---|---|
| 1 | | | | | | | | | | | | | |
| 2 | 6 | 5 | 4 | 3 | 2 | 1 | | | | | | | |
| 3 | | | | | | | | | | | | | |
| 4 | 7 | 8 | 9 | 10 | 11 | 12 | | | | | | | |
| 5 | | | | | | | | | | | | | |
| 6 | 18 | 17 | 16 | 15 | 14 | 13 | | | | | | | |
| 7 | | | | | | | | | | | | | |
| 8 | 19 | 20 | 21 | 22 | 23 | 24 | | | | | | | |
| 9 | | | | | | | | | | | | | |
| 10 | 30 | 29 | 28 | 27 | 26 | 25 | | | | | | | |
| 11 | | | | | | | | | | | | | |
| 12 | 31 | 32 | 33 | 34 | 35 | 36 | | | | | | | |
| 13 | | | | | | | | | | | | | |

I, **Brian Reynolds**, in a field survey on **9 AUGUST, 2000** do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4, and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below.

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1. THE SUBJECT CLOSING 1/4 CORNER WAS NOT ESTABLISHED BY THE GENERAL LAND OFFICE SURVEY.
2. (FOR CORRESPONDING STANDARD CORNER M-6 T2N R7W) GENERAL LAND OFFICE DEPUTY SURVEYOR JOHN MULLETT, 1825, "SUG 24 S42W 17 BEECH 6 N20W 37"
3. THE SUBJECT CLOSING CORNER IS NOT MENTIONED IN THE COUNTY SURVEYOR RECORDS FOR EATON COUNTY.
4. (FOR CORRESPONDING STANDARD CORNER M-6 T2N R7W) BARRY COUNTY SURVEYOR FRANK S. BOWEN, FEBRUARY 2, 1876, LIBER 1 OF SURVEYS, PAGE 137) "SOUTH ON RANDOM FROM N.E. CORNER OF SEC 13...80.42 SEC LINE AT POST...NORTH CORRECTED 40.21 SET 1/4 POST STAKE STONE & CHARCOAL LYNN 36 49 1/2W 58 ROCK ELM 10 N58E 76." DOES NOT MENTION SUBJECT CLOSING CORNER.
5. NO RECORD OF EITHER THE SUBJECT CLOSING CORNER OR THE CORRESPONDING STANDARD CORNER COULD BE FOUND AT EITHER THE BARRY COUNTY ROAD COMMISSION OR THE EATON COUNTY ROAD COMMISSION.
6. (FOR CORRESPONDING STANDARD CORNER M-6 T2N R7W) BARRY COUNTY LAND CORNER RECORDATION CERTIFICATE #450, DATED OCTOBER 1989, RECORDED MARCH 1992, BY KAY DON FLUKE, P.S. #18988, "AFTER TRAVERSING (RETRACEMENT OF COUNTY SURVEYORS SURVEY) AND EXCAVATING, FOUND NOTHING, SET CORNER FROM COUNTY SURVEYORS SURVEYS DATED JANUARY 18, 1876 AND FEBRUARY 2, 1876 AS DONE BY FRANK S. BOWEN. SET 1/2" ROD WITH CAP #18988.....S20E-71.46-2.5FT. x 6FT. ROCK (SW COR.)****S65E-43.34-WALNUT22*****N78E-39.90-POWER POLE ****N10W48.24-WALNUT 12*****NLY-12.7-FENCE POST (R/R TIE..."
7. LAND CORNER RECORDATION CERTIFICATE: BY KAY DON FLUKE, P.S. #18988, 12 MARCH, 1992 (L3, P. 187) "BY USING COUNTY SURVEYOR SURVEY SEC. 13, T2N, R7W, EXCAVATED AND FOUND STONE, SET 1/2" ROD WITH RLS CAP #18988 ALONG SIDE IT. ALSO SET COR. (M-6) T2N, R7W, 4.29 FEET NORTH ALONG SECTION LINE, AFTER EXCAVATING AND FINDING NOTHING." S22E 67.64' SW COR OF 2.5 FT. X 6.0 FT. ROCK S72E 41.81' WALNUT 22 N72E 40.76' POWER POLE N05W 52.46' TWIN WALNUT 12"

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND 1/2" IRON AND MOST WITNESSES BY FLUKE. ACCEPTED FOUND IRON AS BEST AVAILABLE EVIDENCE OF CORNER POSITION. REPLACED FOUND IRON WITH STANDARD EATON COUNTY REMONUMENTATION MONUMENT.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

SET STANDARD EATON COUNTY REMONUMENTATION MONUMENT (3/4" X 36" IRON) WITH ALUMINUM CAP. SOUTHWEST CORNER 2.5' X 6' ROCK S22°E 67.64'
FOUND NAIL & METAL TAG (NO IDENTIFICATION) IN THE NORTH SIDE OF A 24" WALNUT S80°E 41.86'
FOUND NAIL & METAL TAG (NO IDENTIFICATION) IN THE SOUTHEAST SIDE OF A UTILITY POLE N72°E 40.76'
FOUND 1/2" IRON (NO CAP), M-6, T2N, R7W, NORTH 4.38'
A-5 LIES N00°34'46"E 2658.12'
A-7 LIES S00°14'08"W 2658.20'
B-6 LIES S88°22'26"E 2809.73'

[Signature]

Signed by _____
Surveyor's Michigan License No 31602

P.A. 345 EATON COUNTY
PEER APPROVED 8/01/2000 RV

Date AUGUST 16, 2000
FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975 REVISED JANUARY 1983 REVISED OCTOBER 1995

