

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. PA 1970

For Corners In:
Emmet
(County)

Located In

Corner Code #

1. Public Land Survey	T	36N	R	4W	B-8
	T	36N	R	4W	B-9
2. Property Controlling in Section	S	T		R	
	S	T		R	
3. Miscellaneous Property in Section	S	T		R	
	S	T		R	

4. Lot No: Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on June 16, 2008 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

B-8 Not originally set by the GLO.
No other previous information found.

B-9 GLO -1840-John Mullett - Set Post for Corner.
Beech 8 N15°E 7 links
Beech 14 S12°W 30 links

Certificate of Survey-1979-John Ferguson
P.S.#24595-Found 5/8" rod for corner.
8" Maple S12°W 35.88'
26" Maple S50°W 38.73'
P. Pole N70°W 130.28'
7" Ash N65°E 63.50'

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

B-8 Set 5/8"x34" rebar with P.S. cap#33981 per standard BLM procedure. (Intersection of N-S, E-W quarter lines)

B-9 Found 5/8" bar with illegible cap 4' S. of C/L of E-W paved Co. road.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B-8 5/8"x 34" rebar with P.S. cap#33981.
Wit:N4°E 17.40' to set N&T on W side 5" Beech
N89°E 10.49' to set N&T on N side 10" Maple
S40°W 31.98' to set N&T on NW side 9" Maple
N61°W 25.34' to set N&T on N side 8" Maple
Set Blue Carsonite Post with loc. tag 1' North

B-9 Added P.S. cap #33981 to found 5/8" iron bar.
Wit:S18°W 35.79' to set N&T on E side 12" Maple
S67°W 65.56' to set N&T on NW side 12" Maple
N70°W 130.79' to fd. N&T on SW side P.Pole
N39°E 24.45' to set PK&T on W side 6"x6" Post

Signed by:

Carl T. Kiiskila

Surveyor's Michigan License No.: 33981

Date:

7-20-09

