

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Emmet

(County)

Located In

Corner Code #

1. Public Land Survey

T 37 N R 4 W I-4

T 37 N R 4 W I-5

2. Property Controlling  
in Section

S T R

S T R

3. Miscellaneous  
Property in Section

S T R

S T R

4. Lot No:

Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on JUNE 6, 2006 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

I-4 GLO John Mullett DS 1840 set quarter section post.

Wits: 8" Tamarack S54°E 18 Links

7" Cedar S49°W 11 Links

Liber 1, Page 190, 1974 George E. Young RLS #10710

found a 1" pipe with RLS Cap #16051 as set midway and on line by Marvin Ross RLS #16051.

Wits: 18" Maple N55°E 143.73'

8" Pine S25°E 57.89'

I-5 GLO John Mullett DS 1840 set post corner for sections 10, 11, 14 and 15.

Wits: 8" Cedar S14°W 12 Links

10" Cedar S31°E 19 Links

Liber 1, Page 190, 1974, George E. Young RLS #10710 found a 1" iron bar in place.

Wits: 12" Elm N21°E 32.25'

5" Pine S50°E 57.30'

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

I-4 Found 1" pipe with P.S. cap #16051 fitting G.E. Young's survey in section 10.

I-5 Found 1" bar fitting G.E. Young's survey in section 10.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-4 Found 1" pipe with P.S. cap #16051.

Wit: 30" Maple N56°E 143.91'

13" R. Pine S28°E 72.52'

15" Twin R. Pine S54°W 57.32'

8" Cherry N84°W 121.65'

Two track East 25'

R. Pine plantation East 35'

I-5 Found 1" bar

Wits: 10" R. Pine S26°E 35.05'

8" Elm N25°E 11.48'

8" Poplar N34°W 7.03'

3" Maple Clump N49°W 13.41'

3" Cherry S14°W 19.48'

Carsonite post North 1'±

Signed by:

Carl T. Kiiskila

Date:

7/19/06

Surveyor's Michigan License No.:

33981

