

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:
Emmet
(County)

Located In

Corner Code #

1. Public Land Survey T 37N R 5W L-12
T R
2. Property Controlling in Section S T R
S 36 T 37N R 5W 2
3. Miscellaneous Property in Section S T R
S T R

4. Lot No: Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on March 23, 2009 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

L-12 Center 1/4 Corner, Section 36, T37N, R5W

2 - E 1/16 Cor., common to Sec.'s 25 & 36, T37N, R5W

None

None

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

L-12 Center 1/4 Corner, Section 36, T37N, R5W

2 - E 1/16 Cor., common to Sec.'s 25 & 36, T37N, R5W

Set stamped 2" Alum. cap on 5/8"x34" rebar per Standard BLM procedure. Found fence remains running North and West. Fence corner falls +/-50' West and +/-80' South of corner. Found no other evidence to dispute the location for the corner.

Set stamped 2" Alum. cap on 5/8"x34" rebar 0.5' below gravel road surface, per Standard BLM procedure. Found no other evidence to dispute the location for the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L-12 Center 1/4 Corner, Section 36, T37N, R5W

2 - E 1/16 Cor., common to Sec.'s 25 & 36, T37N, R5W

Stamped 2" Aluminum cap on 5/8"x34" rebar
Witnesses:

N31°E 23.66' to set N&T on NW side 11" Ash
S88°E 55.78' to set N&T on N side 12" S.Maple
S03°E 31.39' to set N&T on W side 5" S.Maple
S88°W 29.46' to set N&T on S side 5" S.Maple
S30°W 106' to fence corner.
Set Blue Carsonite Post w/loc. tag 1' North

Stamped 2" Aluminum cap on 5/8"x34" rebar
Witnesses:

N61°E 65.33' to set N&T on NW side 9" Elm
S67°E 73.37' to set N&T on SW side 12" S.Maple
S21°W 62.06' to set N&T on E side 12" R.Pine
N47°W 48.23' to set N&T on NE side 13" S. Maple
Set Blue Carsonite Post w/loc. tag 2305

Signed by:

Carl T. Kiiskila

Date:

7-15-09

Surveyor's Michigan License No.:

33981

