SURVEY & REMONUMENTATION

SECTION

For corners in

MAR 1 3 2000

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN EMMET COUNTY

99 DEC 28 AM 9: 35

Glenna U. Diper	
Sunra a Defect	
REGISTER OF DEEDS	

EMMET Located In: Corner Code # READMOND TOWNSHIP (County) 1. Public Land Survey T<u>37N</u> R 6W ECRP #196 LICER 2. Property Controlling PAGE in Section 3. Miscellaneous Property in Sec. Register of Deeds Stamp & File Number 4. Lot No. _____, Recorded Plat 1 5. Private Claims _ 2 1 3 4 5 in a field survey on Richard E. Oelke 10 December _, 19 <u>99</u>_ do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 6 -14--13 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 B and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a 9 Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, 30... 25 26 found as expressed below: 11 NOTE: Not more that 4 comers, all in the same town and range, may be recorded - 31----33 ... 3່⊿ . 35. 36 on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO set corner in 1840's. Trowbridge found 1" pipe, set by persons unknown, and accepted it as the corner, it has been used in subsequent surveys by local surveyors.

See back page for chronological history of corner.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1" iron pipe, 1.5' long, set by persons unknown, 2' south of the centerline of Division Road at an old fence line north and south.

> 3) S02°W 32.91'

cor fence post, tagged 27463 in E facapproved LAND CORNER P.A. 345 OF 1990

Emmet County RE CELLE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

ECRP. REP.

Set: The 1" pipe noted above was removed, and replaced with a 2" diameter, 30" long, PVC pipe with a base magnet and a standard brass Emmet County Survey Remonumentation Program Cap, which was placed within a standard monument box. This position is accepted as a careful and faithful perpetuation of the position of the original corner.

Additional New Witnesses:

N 00° E, 33.01', 5/8" iron rod capped 33983 N 46° E, 63.16', 8" scotch pine, capped 33983 in NE face S 76° E. 160.48' 20" maple, tagged 33983 in NE face S 00° E, 43.56', 10" maple, tagged 33983 in E face N 26° W, 40.15', 4" w. pine, tagged 33983 in W face



Signed by _____ Date _ 10 December 1999 Surveyor's Michigan License No. 33983

MAR 1 3 2000

LIBER A

SECTION

EMMET COUNTY REMONUMENTATION PROGRAM CORNER NO. 196

37-6-J3 T37N R6W 1/4 cor. bet. 2/11 DIVISION ROAD

Date	Surveyor	Found	Witnesses		<u>Notes</u>
1840	GLO	Set post		., 15" Hemlock , 16" hemlock	
1990	Trowbridge	Survey for Craig (L439,pt	096), fd 1 iron pipe 1) N9°E, 2) N52°E 3) S8°W 4) S47°W	30.63', 47.45', 32.90', 41.11',	tel. pedestal fence post, spk W face cor fence post, spk E face fence post, spk NW face
1990	Trowbridge	LCRC (L2-317), fd +/-1"	pipe, witnessed as al	oove	,
1993	Swenor	Found 1" pipe as witness	sed above		
1997	Oelke	Found 3/4" pipe			