COMPICEION

1996 REMONUMENTATION PROGRAM

LAND (CORNER	RECORDATION	CERTIFICATE

(३(अस्प्रिटी)	1550 1	TELIONOFIEM THE TOTAL TROOP	1117 11 1	¥.		
	LAND COR	NER RECORDATION CER	TIFICATE	10	Dec R	RECORD
F	Filing Requ	irement of Act 74, Mich.	P.A. 1970		الا عالم الا عالم	ORG
For corners in			1:		**1	<i>1</i> 2 2
Genesee	Located In:	Corner Code ≠		, 1	4.4	2.5
	- ON - 6°	16	~		w ·	
Public Land Survey	T <u>8N</u> R <u>6E</u> TR		(2) (2)			72
	T R	*	כע	- 1	96	·
	T R		င္ထာ	,		000
2. Property Controlling	S T R		W	FILED & F	MECONDA	T 9
in Section 3. Miscellaneous	S T R S T R					•
Property in Sec.	S T R		Regis	ter of Deeds S	tamp & File	Number
	Recorded Plat			A B C D	E F G H	IJKL
				2 - 6 5 -		
	* *		,	3		╂┼┼┼┼
. Vouin D. Claryon	a e a sau allanda Moyaml	20 20 10 06	•	<u> </u>	io-	
	? .		tioned	5		
	conformance with regulations	•	in the	7	1 6 15	1-14-1-13-
· · · · · · · · · · · · · · · · · · ·	uctions of the United States Depa a Court of Law and/or that the core	· · · · · · · · · · · · · · · · · · ·	n Lanu	8 19 20	21 22	27 24
	th the rules of the Michigan Board re-established, monumented, re	· · · · · · · · · · · · · · · · · · ·		9		
expressed below:	o ostavnomov, monumentov, te		inu as ti	0 30 29	-2827	2625-
	orners, all in the same town	and range, may be recorded	J	╹├─┼─┼	_ _ _	 - - -
on this certificate.			1:	1 % 1 % 1	-3334	3536-
A. Description of original i	monument and accessories a	nd/or subsequent restoration	n:	3		<u> </u>
	t post with two (2) a		•••			
	I Records, stone/pipe		ssories			
Date ? GE	I Records, five (5) a	accessories				
	I Records, fnd stone					
May 4, 19/9 Sur	rvey, L-2045, P-546 a rvey, L-2057, P-442,	and 54/, ifind 'l' ir - 443 - and 444 - £ddd	on with t	nree (3) a	ccessorie	es coriec
Feb 22. 1980 LC	RC L-2075, P-993, fnd	'T' iron with three	(3) acce	essories	(4) acces	3301 163
Jan 16, 1985 LC	RC L-2276, P-370, fnc	J'T' iron with thre	e (3) acc	essories		
Jul 15, 1988 Sur	rvey, L-2333, P-764 a	and 765, fnd 'T' iro	n with th	ree (3) ac	cessories	5
B. Description of corner ev	vidence found and/or method	applied in restoring or rees	tablishing co	rner:		
Found 'T' iron	in asphalt; found six	(6) accessories fr	om GEI re	cords; fou	nd three	(3)
accessories from	n certified survev. L	iber 2045, Pages 54	6 and 547	: found the	ree (3) 🗋	
accessories from	n certified survey, L n LCRC, Liber 2075, P	iber 2057, Pages 44	2, 443, a	nd 444; for	und three	2 (3)
Liber 2276. Page	a 2075, Found three (3	age 993; round thre D) accessories from	e (3) acc Certified	Survey. I	iber 2333	3.
Pages 764 and 76		, acceptor for from			2000	
Th		de Carrer Carreta D	D			
	und was ratified by t 5, as the accepted co			w committed Ratified by	Poer	Group i
0000001 00, 1550	o, as the accepted co	,	,	accordance		
				Λ	cal N	alm
				Co. Rep.	700	CII
C. Description of monumer	nt for corner and accessories	established to perpetuate to	ocating the po	Date Cosition of the c	- クレー orner:	
						•
	l Bernsten monument S Itation corner 1996 #					
country remonumen	icacion coinci 1330 #	CYCTC III A MUITUMENL	אטא מאהנ	ene Lound	1 17011	:
		sk in power pole				
		orner of concrete he		house Hoos		•
S 30° E 137. S 70° E 79.		ation at northwest orner <u>community</u> heady		nouse #225	7, 3, 7	
J 70 L 794	Li HUI GHERSE C	E OF MICH			14 A. A. A.	
	1	S. Marine			. •	
. /	n AINH	KEVIN BANFIELD CLEAVER	Ļ			:
Signed of Lever Ba	mullillewe	PROFESSIONAL 2	10V 7:	2,1990	0	•
Kevin Banfiel	de legger, P.S., Its	PJ & I da MAYEA GER			T	
Surveyor's Michigan License	NO	29242	FORM APPROVED BY	Y NICHIBAN STATE BOAR		ORS, JAN. 28, 1971
	•	The same of the sa				ISEB MAY 14, 1975 REVISED JAN., 1983