## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In: Gladwin	Located In Com-	0-4-#		
(County)	Located In Corner	Code #		
4. Dublic Land Concess	T 40N D 4E 114			
Public Land Survey	T 18N R 1E H1			
2. Property Controlling				
in Section	S T R S T R S T T R R T T T T R T T T T			
3. Miscellaneous				
Property in Section	S T R R — —			
	3		Register of Deeds S	tamp & File Number
4. Lot No:	Recorded Plat:		A B C D E F G F	IIJKLM
5. Private Claims:		1		
I, <u>Craig W. McVean</u> , in a field survey on <u>Aug. 3</u> , 20 <u>10</u> do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the			7891	01112
			17	14-13-
corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law;				<del></del>
established, re-established	, monumented, recovered, found as expressed b	elow:	19 20 21 2	22324
NOTE: Not more than	2 corners, all in the same town and rang	e. may		
be recorded on this certificate.		e, may <sub>10</sub>	30 29 28 2	7-26-25-
		12	31 32 33 3	36
		13		
A. Description of original monument and accessories and/or subsequent restoration:				
<u>H1</u> - None				
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:				
H1 - Closing 1/4 Corner common to Section 3, T18N. R1E - Set 4" DNR Alum. Cap on 1" x 36" Galv. iron pipe midway between closing				
corner 'G1' and common Standard corner "I-1", T18N, R1E & "I-13", T19N, R1E on the standard line. DNR Monument accepted as the best available evidence of the position of the corner.				
the best available evidence of the position of the corner.				
C. Description of monun	ment for corner and accessories established	to perpetuate locatin	ng the position of the co	rner:
	Aluminum Cap on 1" x 36" long galv. iron pij		I Carolla	- CONTRACTOR OF THE PARTY OF TH
West 2.64' to DNR	Ref Monument at 'H13', T19N, R1E.	be. Det Cedar post i	South	TE OF MICHIGA
	et N & T in SW side 3" Oak et N & T in SE side 5" R. Maple Clp. – 4.		10	CRAIG W.
N24°W 37.23' to s	et N & T in E. side 3" Oak		12/	McVEAN #
S6°E 22.87' to set N & T in W, side 2" Oak  PROFESSIONAL SURVEYOR  NO				
				No.
			A 34	39088
	<u> </u>		100	OFESSIONAL
//	( ) . Mai Ma 4/1		, ,	A CONTRACTOR OF THE PARTY OF TH
Signed by:	me W Ille V.	Date: //	126/2012	
Surveyor's Michigan			1-10	