

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In: Gladwin Located In Corner Code #
(County)

1. Public Land Survey T 18N R 1E I-2
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Section S T R

4. Lot No: Recorded Plat:

5. Private Claims:

I, Craig W. McVean, in a field survey on Aug. 16, 2010 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

I-2 - 1846 - GLO - J. Mullet - Set ¼ post
1) Beech 8" N34°W 22 L.
2) Beech 6" N61°E 23 L.
- 1930's - CCC - South 22:00 - Set random ¼ post

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

I-2 - ¼ corner common to sections 2 & 3, T18N, R1E - Searched area and found no evidence of a corner or GLO BT's. Set a 4" stamped Aluminum DNR cap on 1" x 36" galvanized iron pipe by single proportion to GLO between 'I-1' and 'I-3'. Grid distance North 1440.27' (1452' - GLO) to 'I-1' and South 2618.68' (2640' - GLO) to 'I-3'. DNR monument accepted as a careful and faithful re-establishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-2 - Stamped 4" Aluminum DNR cap on a 1" x 36" galvanized iron pipe
S73°E 6.79' to set Nail & Tag in S. side 6" Oak scribed 'XBT'
N31°E 14.30' to set Nail & Tag in S. side 6" Red Maple in a clump of 4
N74°W 23.68' to set Nail & Tag in N. side 6" Oak scribed 'XBT'
S03°W 15.30' to set Nail & Tag in E. side 16" Oak scribed 'XBT'
Set Blue Carsonite Post 1' Northwest



Signed by:

Craig W. McVean

Date:

1/26/2012

Surveyor's Michigan License No.:

39088