

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. PA 1970

Gladwin
(County)

Located In

Corner Code #

1. Public Land Survey T 18N R 1E L1
T
2. Property Controlling in Section S T R
S T R
3. Miscellaneous Property in Section S T R
S T R

4. Lot No: Recorded Plat:

5. Private Claims:

I, Craig W. McVean, in a field survey on Feb. 14, 2011 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

Register of Deeds Stamp & File Number

A. Description of original monument and accessories and/or subsequent restoration:

L1 - None

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

L1 - Closing 1/4 Corner common to Section 1, T18N, R1E - Set 4" DNR Alum. Cap on 1" x 5' long iron pipe midway between 'K1' and 'M1' on standard line. Corner in Maple and Ash swamp. DNR Monument accepted as the best available evidence of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L1 - 4" DNR Aluminum Cap on 1" x 5' long galv. iron pipe
East 5.28' to "L13", T19N, R1E - DNR Mon.
N20°E 20.46' to set N & T in W. side 8" R. Maple
N78°E 25.09' to set N & T in N. side 6" R. Maple scribed 'XBT'
S2°W 30.61' to set N & T in E. side 10" R. Maple
S69°W 8.51' to set N & T in S. side 4" R. Maple scribed 'XBT'
Set Blue Carsonite Post 1' South



Signed by:

Craig W. McVean

Date:

1/26/2012

Surveyor's Michigan License No.:

39088