

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Gladwin

(County)

Located In

Corner Code #

1. Public Land Survey

T

R

T

R

2. Property Controlling  
in Section

S 2

T

18N

R 1E

12

S 2

T

18N

R 1E

15

3. Miscellaneous

Property in Section

S

T

R

S

T

R

4. Lot No:

Recorded Plat:

5. Private Claims:

I, Craig W. McVean, in a field survey on Oct. 21, 2010 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

Register of Deeds Stamp & File Number

|    | A  | B | C  | D | E  | F | G  | H | I  | J | K  | L | M |
|----|----|---|----|---|----|---|----|---|----|---|----|---|---|
| 1  |    |   |    |   |    |   |    |   |    |   |    |   |   |
| 2  | 6  |   | 5  |   | 4  |   | 3  |   | 2  |   | 1  |   |   |
| 3  |    |   |    |   |    |   |    |   |    |   |    |   |   |
| 4  | 7  |   | 8  |   | 9  |   | 10 |   | 11 |   | 12 |   |   |
| 5  |    |   |    |   |    |   |    |   |    |   |    |   |   |
| 6  | 18 |   | 17 |   | 16 |   | 15 |   | 14 |   | 13 |   |   |
| 7  |    |   |    |   |    |   |    |   |    |   |    |   |   |
| 8  | 19 |   | 20 |   | 21 |   | 22 |   | 23 |   | 24 |   |   |
| 9  |    |   |    |   |    |   |    |   |    |   |    |   |   |
| 10 | 30 |   | 29 |   | 28 |   | 27 |   | 26 |   | 25 |   |   |
| 11 |    |   |    |   |    |   |    |   |    |   |    |   |   |
| 12 | 31 |   | 32 |   | 33 |   | 34 |   | 35 |   | 36 |   |   |
| 13 |    |   |    |   |    |   |    |   |    |   |    |   |   |

A. Description of original monument and accessories and/or subsequent restoration:

12 - None

15 - None



B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

12 - CS 1/16 Corner Sec. 2, T18N, R1E - Set 2" Alum. Cap on 5/8" x 34" long iron rebar per Standard BLM procedure. Corner near Top of Bank. West 39'± to E. Bank of Stream.

15 - W 1/16 Corner common to Sec. 2 & 11, T18N, R1E - Set 2" Alum. Cap on 5/8" x 34" long iron rebar per standard BLM procedure. E-W Single Strand is 5' N. 4" x 4" steel post for single strand N & W is 48' to East and 5'± N.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

12 - Stamped 2" Alum. Cap on 5/8" x 34" long iron rebar N11°E 39.88' to set N & T in E. side 8" Oak East 20.15' to set N & T in N. side 4" Oak S18°E 45.02' to set N & T in W. side 4" Oak S20°W 30.28' to set N & T in E. side Tw. 9" Maple Set Blue Carsonite Post with Loc. tag 1' SE

15 - Stamped 2" Alum. Cap on 5/8" x 34" long iron rebar N2°E 46.75' to set N & T in E. side 6" Oak N70°E 8.36' to set N & T in S. side 9" Oak S5°E 39.84' to set N & T in S. side 15" Oak S68°W 69.39' to set N & T in S. side 8" W. Pine Set Cedar post with loc. tag 1' SE

Signed by:

Craig W. McVean

Date:

11/29/2012

Surveyor's Michigan License No.:

39088