

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
GLADWIN

(County)

Located in:

Corner Code ≠

1. Public Land Survey

T 18N R 2E

E-3, E-4,

T R

F-4

T R

T R

2. Property Controlling
in Section

S 9 T R

8

S T R

3. Miscellaneous

S T R

Property in Sec:

S T R

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, C.T. KIISKILA, in a field survey on JULY 29, 19 94,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

E-3

E-4

F-4

(NO CONCLUSIVE EVIDENCE OF G.L.O. CORNER MONUMENT, CORNER BT'S,
LINE TREES, TOPOGRAPHY, ETC. AS CALLED OUT IN THE G.L.O. LINE
NOTES; UNLESS NOTED IN ITEM "B" BELOW.)

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	18	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

8



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E-3

E-4

F-4

8

REESTABLISHED NE COR SEC 8 PER
PS, J. MEYERS SEC 9
SUBDIVISION. COR FITS VERY
REASONABLE TO PROPORTIONATE US
MEASURE BETWEEN FB SEC COR 1
MI E, 1 MI W, AND 1 MI N; NE,
SEC 5.

FD PIPE FOR W 1/4 COR SEC 9.
PIPE FITS TWO J. MEYERS WITS
(ONE NOW A STP & ONE DOWN) &
HIS RECORD DATA PER CERT OF
SURVEY RECORDED LI.2, PG. 459.
CTR OF M-61 IS 108' SOUTH.

FB AND ACCEPTED 1/2" REROD FOR
CTR SEC 9. COR FITS P.S.
P. LAPHAM & ASSOCIATES SEC 9
SUBDIVISION. CTR M-61 (28'
WIDE BIT) IS 138' SOUTH.

FOUND REROD WITH P.S.
L. URBANIAX'S CAP FOR NE
CORNER OF W 1/2 OF SW 1/4 OF
SEC 9. CTR OF M-61 IS 123'
SOUTH

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-3

E-4

F-4

8

SET DNR MON & CED POST.

FD 1/4" GALV PIPE. ADDED DNR
MON. SET CED POST.

FD 1/2" REROD W/RLS CAP &
STEEL FN POST FOR GUARD. ADDED
CED POST W/LDC TAG.

FD 1/2" REROD W/RLS CAP &
STEEL FN POST FOR GUARD. ADDED
CED POST W/LDC TAG.

19" TN B. OAK N70°W 113.7'
11" J PINE N05°W 25.3'
16" R PINE S25°E 168.0'
14" B CHERRY S20°W 108.2'

6" MAPLE N25°E 18.5'
5" MAPLE S10°E 17.3'
5" B CHERRY S20°W 16.0'
5" TN MAPLE S80°W 12.6'

3" B OAK N20°W 12.7'
4" B OAK S05°E 32.8'
4" B OAK S25°W 25.7'
3" B OAK S85°W 25.0'

6" B OAK N05°E 31.6'
4" B OAK N60°E 34.7'
6" B CHERRY S60°E 7.3'
8" B CHERRY S10°W 11.7'

Signed by

Carl T. Kiiskila

Date

3-28-97

Surveyor's Michigan License No.

33981