

GLADWIN COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

UBER 001 PAGE 161

For corners in

GLADWIN

(County)

Located In:

Corner Code #

1. Public Land Survey

T 18N R 1W

C-5

2. Property Controlling
in Section

S

T R

3. Miscellaneous
Property in Sec.

S

T R

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____STATE OF MICHIGAN
GLADWIN COUNTY
FILED Remonumentation

17 OCT 97 1:18 P.M.

BONNIE K. HOUSE
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, MARK R. ROBISON, in a field survey on April 18, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

1877 T. Gale Merrill
Set Post
Wit.-(1)N80E 17 links 17" Pine
(2)N50W 7 links - 13" W. Pine

1980 Lapham working drwg & witnesses
Wit.-(4)S Corner Post 25.12'
(5)S45E Fence Post 41.30'
(6)N15W 10" Poplar 47.35'

1907 County Survey Records
Fnd 3' x 3" x 3" Cedar Stake
Wit.-(3)N40W 50 Links 18" Pine Stump

1981 Lapham working drawing

1992 Lapham survey & working drwg.
Wit.-same as (4),(5)&(6)

APPROVED LAND CORNER
P.A. 345 of 1990
Gladwin County

Co. Rep. John Meyers
Date 9/25/97

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2" x 18" rerod in centerline of county road opposite old fence corner and fenceline South. Found (4); measured 25.6', post leaning, recorded 25.12'. Set Gladwin County Re-mon in place of found iron.

See dossier for detailed report.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-5: Corner common to Sections 7, 8, 17 & 18.
Set 5/8" x 36" rerod with Gladwin County Re-mon Cap marked P.S.#27458

Witnesses:

North 18" W. Pine, nail & tag, 71.80'
N22E 16" W. Pine, nail & tag, 97.66'
S50E 8" W. Pine, nail & tag, 70.18'
S10E 5" Pine, nail & tag, 76.65'

Signed by

Surveyor's Michigan License No. 27458

Date

10-7-97SURVEY &
REMONUMENTATION

JAN 08 1998

SECTION