

SURVEY & REMONUMENTATION

GLADWIN COUNTY REMONUMENTATION

DEC 16 1996

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

701 PAGE 116

For corners in

COMMISSION

GLADWIN

(County)

Located In:

Corner Code #

1. Public Land Survey

T 20N R 1E E - 1

T R

T R

T R

2. Property Controlling in Section

S T R

S T R

3. Miscellaneous Property in Sec.

S T R

S T R

4. Lot No. , Recorded Plat

5. Private Claims

I, MARK ROBISON, in a field survey on November, 1996 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1836 JOHN MULLETT
WIT.-(1)PINE 30 N33W 20
(2)S MAPLE 12 N43E 51

SECTION SUBDIVISION

1950 OSTLING SURVEY
FOUND ORIGINAL POST
PLACED 4" X 48" SQD POST
WIT.-(3)BLAZE 20" N. PINE S80W 26.9
(4)BLAZE 8" CEDAR S16W 13.2

1991 ARLETH SURVEY
FOUND OLD POST
SET 3/4" X 44" PIPE
WIT.-(5)SP. IN 10" CEDAR ESE 12.65
(6)SP. IN 10" CEDAR SSW 13.20
(7)SP. IN 24" N. PINE WSW 27.55

1970 PAUL LAPHAM

1992 PAUL LAPHAM SURVEY
WIT.-SAME AS (5),(6)&(7)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.

FOUND 3/4" PIPE & SQUARE WOOD POST AT BASE OF 10" FENCE CORNER POST. FOUND WITNESSES (3)&(7). SET GLADWIN RE-MON FROM FOUND CORNER & WITNESSES (3)&(7).

SEE DOSSIER FOR DETAILED REPORT.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-1: NW CORNER OF SECTION 4
SET 5/8" X 36" REROD WITH GLADWIN RE-MON CAP MARKED P.S.#27458

WITNESSES:
S15E 24" W. PINE, N&T, 40.70'
N80E 24" W. OAK, N&T, 33.80'
S45W 18" OAK, N&T, 43.30'
S85W 20" PINE STUMP (F.J.A. CAP) 27.55'

Signed by Mark R. Robison

Surveyor's Michigan License No. 27458

Date 11-29-96

STATE OF MICHIGAN
GLADWIN COUNTY
FILED-REMONUMENTATION

2 DEC 96 3:26 P.M.

BONNIE K. HOUSE
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5		4		3		2		1	
3													
4	7			8		9		10		11		12	
5													
6	18			17		16		15		14		13	
7													
8	19			20		21		22		23		24	
9													
10	30			29		28		27		26		25	
11													
12	31			32		33		34		35		36	
13													

1992 PAUL LAPHAM SURVEY
WIT.-SAME AS (5),(6)&(7)

APPROVED LAND CORNER
P.A. 346 of 1990
Gladwin County

Co Rep. Mark R. Robison
Date 11/6/96

