

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. PA 1970

For Corners In: Gladwin (County) Located In Corner Code #
1. Public Land Survey T 20N R 2E C13
2. Property Controlling in Section S T R
3. Miscellaneous Property in Section S T R
4. Lot No: Recorded Plat:
5. Private Claims:

I, Craig W. McVean, in a field survey on April 19, 2006 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Table with 13 rows and 13 columns (A-M). Contains numbers 1-36 in a grid pattern, with a small black dot in cell C12.

A. Description of original monument and accessories and/or subsequent restoration:

C13 - GLO - Set Post - L. Clason - 1837
Elm 9" N17°E 15 L.
Elm 8" N18°W 15 L.
(CC is 6 L. West)
- CCC Notes - 1930's - West on N. Bdy of Sec. 5, T19N, R2E. 400.00 - Set Random Mile Post. Random post is 2:66 S. and 1:47 W. of post.
- LCRC - #11 - K. J. Ostling - 1971
Fd. 3/4" pipe in centerline of Rd. N, E & W - slightly W. of centerline Rd. - S.; 1/2" rod in Sq. Conc. Mon.
N46°E 41.1'; Face of P.P. N40°W 46.15; 1 1/4" pipe West 3.96'
- Rec. Sur - L. 2, P. 12 - P. B. Lapham - 1980
Fd. 3/4" pipe. Same Wits as Ostling.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

C13 - Standard Corner common to Sec. 31 & 32 - Fd. 3/4" iron pipe in Mon. Box per Lapham and Ostling. No GLO evidence. In line with centerline Bit. Rd. West and Gravel Rd. East. Just E. of centerline of Bit. Rd. N. 3/4" iron pipe accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C13 - Drove stamped 2 1/2" DNR Brass Cap on 5/8" x 24" rebar into found 3/4" pipe in Mon. Box.
West 3.96' to 'C1', T19N, R2E - 2 1/2" Brass Cap in Mon. Box
N41°W 46.71' to set N & T in SW side P.P. (KJO, PBL)
N29°W 67.36' to set epoxied tag in top Conc. Proj. Marker
N37°E 80.26' to set N & T in NW side 14" Maple
S51°E 56.26' to set N & T in NE side 9" R. Maple
S45°W 112.50' to NE Cor. Conc. Hse. FNDD.



Signed by: [Signature] Date: 5/9/2007
Surveyor's Michigan License No.: 39088