

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. PA 1970

For Corners In: Gladwin (County) Located In Corner Code #
1. Public Land Survey T 20N R 2E E13
2. Property Controlling in Section S T R
3. Miscellaneous Property in Section S T R
4. Lot No: Recorded Plat:
5. Private Claims:

Register of Deeds Stamp & File Number

Table with 13 rows and 13 columns (A-M). Contains numbers 1-36 in a grid pattern, with a small black dot in cell F12.

I, Craig W. McVean, in a field survey on Nov. 7, 2005 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

E13 - GLO - L. Clason - 1837
Hemlock 12" N64°E 30 L.
Hemlock 11" N56°W 29 L.
(Closing Corner is 40 L. West)
- CCC Notes - 1930's - Run N. from corner. W. on N. boundary of Sec. 4. 320:00 - Set random mile post. Random post is 1.17 1/2 W & 2.09 S. of post.
- DNR Corner record - K. J. Ostling - 1970 - Fd. - 2" x 18" pipe in centerline road, bent over by grader, as established in some previous survey by persons unknown. Fits very well for proportional measurement for 2 miles on S. side Sec. 32 & 33.
Set DNR Monument.
16" WPS N30°W 62.7'
16" WPS N70°E 72.5'
Corner Sec. 4- - 5, T19N, R2E is 26.4 West.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

E13 - Standard corner common to Sec. 32 & 33, T20N, R2E - fd. N'ly leaning 2" x 14" iron pipe in centerline E-W gravel rd. - 0.3' below surface. Straighten up for point. No evidence of DNR Monument. Fits one fd. Ostling witness. No GLO evidence. 2" iron pipe accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E13 - Replaced 2" x 14" pipe with 2 1/2" DNR Brass Cap on 5/8" x 34" rebar w/ 4" x 0.6' PVC w/ conc. around cap - down 0.6'
S60°W 43.48' to chiseled 'X' in NE face 5" pipe post
N6°E 29.04' to set N & T in W. side 7" R. Maple
N30°W 63.60' to set N & T in E. side 16" WPS (KJO)
N55°E 33.96' to set N & T in NW side 4" Oak
S8°E 17.58' to set N & T in E. side tri 6" R. Maple
Set Blue Carsonite Post w/ loc. tag 33' N.
West 26.48' (26.4' - GLO) to 'E1', T19N, R2E - 2 1/2" Brass Cap



Signed by: Craig W. McVean
Surveyor's Michigan License No.: 39088

Date: 5/9/2007