

SURVEY &  
REMONUMENTATION

DEC 16 1996

COMMISSION

GLADWIN COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

GLADWIN

(County)

Located in:

Corner Code #

1. Public Land Survey

|   |     |   |    |        |
|---|-----|---|----|--------|
| T | 20N | R | 1W | F - 11 |
| T |     | R |    |        |
| T |     | R |    |        |
| T |     | R |    |        |
| S |     | T | R  |        |
| S |     | T | R  |        |
| S |     | T | R  |        |
| S |     | T | R  |        |

2. Property Controlling  
in Section

3. Miscellaneous  
Property in Sec.

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

LIBER 001 PAGE 150

STATE OF MICHIGAN  
GLADWIN COUNTY  
FILED-REMONUMENTATION

2 DEC 96 3:34 P.M.

DONNIE K. HOUSE  
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, MARK ROBISON, in a field survey on November, 1996 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

|    |   |    |   |    |   |    |   |    |   |    |   |    |   |
|----|---|----|---|----|---|----|---|----|---|----|---|----|---|
| 1  | A | B  | C | D  | E | F  | G | H  | I | J  | K | L  | M |
| 2  |   | 5  |   | 5  |   | 4  |   | 3  |   | 2  |   | 1  |   |
| 3  |   |    |   |    |   |    |   |    |   |    |   |    |   |
| 4  |   | 7  |   | 8  |   | 9  |   | 10 |   | 11 |   | 12 |   |
| 5  |   |    |   |    |   |    |   |    |   |    |   |    |   |
| 6  |   | 18 |   | 17 |   | 16 |   | 15 |   | 14 |   | 13 |   |
| 7  |   |    |   |    |   |    |   |    |   |    |   |    |   |
| 8  |   | 19 |   | 20 |   | 21 |   | 22 |   | 23 |   | 24 |   |
| 9  |   |    |   |    |   |    |   |    |   |    |   |    |   |
| 10 |   | 30 |   | 29 |   | 28 |   | 27 |   | 26 |   | 25 |   |
| 11 |   |    |   |    |   |    |   |    |   |    |   |    |   |
| 12 |   | 31 |   | 32 |   | 33 |   | 34 |   | 35 |   | 36 |   |
| 13 |   |    |   |    |   |    |   |    |   |    |   |    |   |

A. Description of original monument and accessories and/or subsequent restoration:

1858 GEO E. ADAIR

SET 1/4 POST

WIT.-(1)WHITE PINE 15 N34E 15

(2)CEDAR 7 S35E 8

FOUND 4" X 1/4" FLAT IRON

RAISED WITH 1/2" BAR R.L.S.

WIT.-(5)N75W 138.73 P.P.

(6)NORTH 1/2" BAR R.L.S. 33.00

(7)N85E 233.37 POWER POLE

1950 DUNDAS & EDMANDS ENG.

NO COR MATERIAL

WIT.-(3)TACK IN FENCE POST NE 82.56

(4)TACK IN 4th FENCE POST SE 69.64

1978 SEDGMAN

WIT.-SAME AS (5),(6)&(7)

1978 SEDGMAN

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND 4" X 1/4" FLAT IRON RAISED WITH 1/2" X 16" C.I. 12" BELOW SURFACE IN C/L OF GRAVEL COUNTY ROAD FIELD LINE SOUTH. REMOVED C.I., LEFT FLAT IRON,  
SET GLADWIN RE-MON OVER FLAT IRON.

SEE DOSSIER FOR DETAILED REPORT.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F-11: 1/4 CORNER COMMON TO SECTIONS 28 & 33

SET 5/8" X 36" REROD WITH GLADWIN COUNTY RE-MON CAP MARKED P.S.#27458

WITNESSES:

N75W POWER POLE, N&T, 135.75'

N80E POWER POLE, N&T, 238.64'

SOUTH 10" ELM, N&T, 121.55'

S55E 1/2" X 18" REROD 62.30'



Signed by

Mark R. Robison

Surveyor's Michigan License No.

27458

Date

11-29-96