

SURVEY & REMONUMENTATION

NOV 12 1997

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>Gogebic</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T43N R 38W	EE 5-6
	T R	Other
	T R	# 010
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous	S T R	
Property in Sec.	S T R	

Register's Office } ss.
Gogebic County

Received for record the
27TH day of OCTOBER
A. D. 1997 at 11:15 o'clock
A m., and recorded in
Lib. 6 of CORNERS
on page 254
Ramona Collins, Deputy
Register of Deeds

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

Mile Corner #12, Michigan-----Wisconsin State Line

I, Gary L. Pisoni, in a field survey on June 27, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Corner established by William Burt in 1847.
Original bearing trees:
Cedar 12" S 84°W 24 links (15.84 feet)
Cedar 10" N 05°W 19 links (12.54 feet)

Corner restored in 1928 by Earl G. Harrington by proportional measurement methods. No evidence of original B.T.s found. He set a standard brass capped concrete monument and two new B.T.s.
Cedar 10" S 24°40'W 25 links (16.5 feet)
Cedar 10" S 78°30'E 27.1 links (17.9 feet)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Recovered the 1928 standard brass capped concrete monument as described in Harrington's notes. The 1928 cedar B.T. is now a live 16" cedar, S 74°E, 18.62 feet, blazes grown over; and a live 14" cedar, S 25°W, 15.62 feet, blazes grown over.

No evidence remains of the 1847 B.T.s.

Corner Record Research on file with County Representative.

Found bearing trees referencing Mile Corner position:
Cedar 12" N 31°W 34.00 feet
Cedar 15" N 69°E 36.02 feet
Steel sign post S 72°W 1.1 feet

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

PEER GROUP APPROVED
Richard L. Dean 10/8/97
COUNTY REPRESENTATIVE



97-09
Signed by Gary L. Pisoni Date 7-15-97
Surveyor's Michigan License No. 27457