

SURVEY & REMONUMENTATION

DEC 15 1998

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>Gogebic</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T <u>43N</u> R <u>39W</u>	<u>D-E, 1-2</u>
	T <u> </u> R <u> </u>	<u> </u>
	T <u> </u> R <u> </u>	<u>00A</u>
	T <u> </u> R <u> </u>	<u> </u>
2. Property Controlling in Section	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
3. Miscellaneous Property in Sec.	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
	S <u> </u> T <u> </u> R <u> </u>	<u> </u>

Register's Office } ss.
Gogebic County }

Received for record the
4th day of NOVEMBER
A. D. 1998 at 3:20 o'clock
P m., and recorded in
Liber 7 of CORNERS
on page 81
Amelia Collins, Deputy
Register of Deeds

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

Mile Corner # 45 1/2, Wisc.- Mich. State Line, T43N-R39W

I, Gary L. Pisoni, in a field survey on October 16, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established by William A. Burt, U.S. Deputy Surveyor in 1847

The State boundary line as originally surveyed was retraced and re-established under the direction of the Michigan-Wisconsin Boundary Commission, by Earl G. Harrington, Cadastral Engineer in 1928-1929. Mile Corner No. 45 1/2 which is a concrete monument 26" long, 6" square at the top, 7 1/2" square at the base, fitted with a metal tablet marked for Mile Corner No. 45 1/2.

1928 Bearing Trees:	Spruce	8"	S 00° 40' E	29.4 feet
	Norway Pine	18"	N 64° 50' W	163.7 feet

On 10/10/67, Donald D. Lappala RLS with the U.S. Forest Service restored the corner position from the above described monument and found a live Red Pine and a Spruce stump as described above.

1967 Bearing Trees:	Tamarack	11"	N 22° W	24.6 feet
	Spruce	4"	S 82° E	28.5 feet
	Tamarack	8"	S 50° W	25.8 feet

PEER GROUP APPROVAL
Richard L. Wrahn 10/27/98
COUNTY SEVEN

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence of Spruce Stump found; found a live 30" Red Pine (Norway Pine) bearing tree as described above.

On 10/16/98, found the monument as described above, 8" above ground surface and the following bearing objects: (All measurements taken to a nail in side of tree):

Tamarack	14"	N 25° W	24.54 feet
Wood sign post	4"x4"	N 20° E	1.60 feet

Corner record research on file with County Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Blazed and scribed the following new bearing trees: (All measurements taken to a nail in side of tree)

Black Spruce	13"	S 61° E	27.27 feet
Tamarack	11"	S 30° W	29.72 feet
Steel sign post	6'	N 73° E	0.75 feet

98-G9
Signed by Gary L. Pisoni Date October 24, 1998

Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1991

