

SURVEY &  
REMONUMENTATION  
APR 07 1995  
COMMISSION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in  
Gogebic  
(County)

Located In: R.R. Corner Code #

- Public Land Survey  
Section 1  
T 44N R 41W  
T      R       
T      R       
T      R
- Property Controlling  
in Section  
S      T      R       
S      T      R
- Miscellaneous  
Property in Sec.  
S      T      R

K-2  
M-3  
#004  
004  
R 12  
10/18/98

Register's Office } ss.  
Gogebic County }

Received for record the  
21<sup>st</sup> day of OCTOBER  
A. D. 1994 at 11:15 o'clock  
A m., and recorded in  
Liber 5 of CORNERS  
on page 143  
Ramona Collins, Deputy  
Register of Deeds

Register of Deeds Stamp & File Number

- Lot No.     , Recorded Plat
- Private Claims

M.C. to sec's. 1 and 12

I, John P. Goss, in a field survey on September 18, 1994,  
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned  
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the  
current manual of survey instructions of the United States Department of the Interior, Bureau of Land  
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5  
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a  
Court of Law; established, re-established, monumented, re-monumented, recovered, found as  
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded  
on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original survey by Algemon Merryweather. Elm 6" corner tree. In 1852.  
Original bearing tree  
Balsam 8" S30°W 8 links

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1" iron pipe set by Northwood surveyor's Inc. in subdivision of sec's.  
1 and 12 in 1973. Witness 9" cedar, N11°E, 22.7'.  
Replaced by 4" concrete monument with red cap in 1979 as part of Plat  
of Maplewood by Inman-Foltz and Associates, Inc.  
This point has been used by Gogebic County Road Commission and other  
surveyors in the area.

Act 74 research on file with the County Register of Deeds Office.

PEER GROUP

Approved

Richard P. D. [Signature]

10/12/94

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I removed the concrete monument and cap and set in it's place a  
2 1/2" x 30" long aluminum pipe with a 3 1/4" aluminum cap stamped  
M.C., S-1, S-12, 1994, P.S. 23509. I established the following bearing  
trees and reference object:

D.H. nail & tag 13" cedar	N11°E	23.34'
D.H. nail & tag 7" spruce	N61°W	13.03'
D.H. nail & tag 5" W. Birch	S53°W	2.53'
D.H. nail & tag 11" hemlock	S51°E	6.00'
Steel sign post	Due W	0.93'



Signed by John P. Goss  
Surveyor's Michigan License No. P.S. 23509

Date 9-24-94