5 Sec. 1

		LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970				Received for record the										
For corner	s in		·													
Gogebic (County)		Located In: Corner Code =##			A.					124 and 1						
1. Public	Land Survey	T <u>44N R 41W</u> T R (	G=5,6 013 R & D, 10/18/48		<b>66</b> 2	er_ per	3	6	4 1. K	_0[_ 2101	Co	en Ve	<u> </u>	•		
in Sect 3. Miscell		PEER-GROUP  Rocland D. Dralm	Approved—	Regist	ter	of D	eed	is S		giste ip & i						
4. Lot No	R	ecorded Plat				R	c	D	E F	F G	н	l J	ı K	,		
5. Private	Claims				ŕ	Ť	ŤΤ		П	Ť	Ϋ́	Ť		Ť	_	
0	C 5 6 (N	orth Meander Corner bet	tween Sections 15 and 1	6 . 2	2	- 6	-	<u>;</u> —	<del> </del>		- 3 —	+	<u> </u>	[		
COIN					³├			$\vdash$			+-	╂		$\dashv$	_	
	O	n the South shore of L	Indstey Lake,	4	<b>4</b> لـــ	. <del> </del>	<u>.</u>	<u>i</u> _	L	-	-10- <del>-</del> -	ւ	١	12	<u> </u>	
ı Garv	L. Pisoni .	in a field survey onDecember	er 21 19 <u>93</u> .	:	۶L			Ш			$\perp$					
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the						-18		7-	  16	, •	-1 <b>5</b>	1	 	13 	}	
current manual of survey instructions of the United States Department of the Interior, Bureau of Land						1-					十	<del></del>				
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a						-19	-2	┍╌╢	21	-	-22-	1-2	3	24	<b>-</b> -	
		e-established, monumented, re-mo		9	╸├	+-	-		H	-	+	╂	-	$\dashv$		

Original corner established by A. Merryweather, U.S. Deputy Surveyor on July 5, 1852.

Original corner: Set Meander Corner

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

A. Description of original monument and accessories and/or subsequent restoration:

Original bearing trees:

on this certificate.

No bearing trees listed in original survey field notes.

8. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No original corner evidence found. Corner position found marked by a 1" diameter iron pipe located on the South shore of Lindsley Lake. Iron pipe set by unknown person. Iron pipe has been used for numerous surveys in Sections 15 and 16. I accept the iron pipe as the best available evidence for restoring the corner position.

Set aluminum rod monument inside of iron pipe. Monument located 6 feet from waters edge.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position, I set a 3/4" outside diameter by 3 feet long aluminum rod monument with a 3" cast aluminum cap, stamped to read: T44N, R4lW, M.C., S-16,S-15, 1993, RLS- 27457 from which I established the following new blazed and scribed

bearing trees: (all measurements taken to a nail in side of tree)

Hemlock 12" S 67°E 30.02 feet

Hemlock" 14" S 35°E 24.12 feet s 20°W 10" 40.47 feet Cedar North 1.10 feet Steel Sign Post

Date

GARY L. PISONI LAND SURVEYOR ENFO LAND

Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEY RVEYDRS, JAN. 28, 1971

BEVISED MAY 14, 1975