

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Gogebic Located In: Corner Code ##
(County)
1. Public Land Survey T 44N R 41W J,K-7
T R 016
T R 016
2. Property Controlling S T R
in Section S T R REX
3. Miscellaneous S T R 10/18/98
Property in Sec. S T R

Register's Office } ss.
Gogebic County }

Received for record the
12TH day of CORNERS
A. D. 1995 at 2:00 o'clock
P. m., and recorded in
Liber 5 of CORNERS
on page 252
Ramona Collins, Deputy
Register of Deeds
Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

Corner J,K-7 (East Meander Corner between Sections 14 & 23
on the East shore of East Bay Lake)

I, Gary L. Pisoni, in a field survey on November 4, 19 93,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established by Algernon Merryweather, U.S. Deputy Surveyor on June 28, 1952.
Original corner: 20" Cedar corner tree
Original Bearing tree:
Balsam 6" N 40°E 12 lks (7.92 feet)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No original corner evidence found. Corner position found by a 2 inch diameter wood post
located on the East shore of East Bay Lake. Wood post set by unknown person. I accept
the wood post as the best available evidence for restoring the corner position.

PEER GROUP APPROVED
Richard P. Dush 4/6/95
COUNTY REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position, I set a 2 inch diameter by 30 inch long split base aluminum pipe
monument with a 3 inch diameter cast aluminum cap, stamped to read: T44N, R41W, M.C.,
S-14, S-23, 1993, RIS- 27457 from which I established the following new blazed and scribed
bearing trees: (all measurements taken to a nail in side of tree)

Cedar	13"	N 26°W	7.70 feet
Cedar	10"	N 62°E	9.91 feet
Cedar	10"	S 13°W	29.28 feet
Steel Sign Post		East	1.00 feet



Signed by Gary L. Pisoni

Date March 29, 1995

Surveyor's Michigan License No. 27457