

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

Register's Office }
Gogebic County }

For corners in
Gogebic
(County)

Located in: Corner Code #

1. Public Land Survey T44NR41W H-1-5
T R 021
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

**SURVEY &
REMONUMENTATION**

JAN 05 2001

Received for record the
4TH day of DECEMBER
A. D. 2000 at 10:45 o'clock
A m., and recorded in
Liber 8 of CORNERS
on page 45
Ramona L. Collins, Deputy
Register of Deeds

Register of Deeds Stamp & File
Number

4. Lot No. _____, Recorded Plat _____ **SECTION**
5. Private Claims _____
West Witness Meander Corner common to Sections 10 and 15 on
the East side of Fish Hawk Lake.

I, John R. Garske, in a field survey on November 29, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and / or that the corner points mentioned in lines 3, 4, and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below.

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and / or subsequent restoration:

Original survey by Algernon Merryweather in June - July 1852.
Original corner: Cedar 8" diameter corner tree at 16.35 chains going West
Original bearing trees: 7" Hemlock S 70°E 3 Links

REBAR GROUP ATTACHED
Richard P. Dral 11/29/00
COURT RECORDED

B. Description of corner evidence found and / or method applied in restoring or re-establishing corner:

I found a 5/8" rebar set by others. I accepted the following position as a witness meander corner. GLO bearing and distance from the Northeast section corner to the meander corner is West at 1079.10 feet; measured being N 89°-53'-40"W at 1059.99 feet. We also found a wood post and iron pipe at the water's edge 8.97 feet West on the monumented position. Record research on file.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I accepted the position of the 5/8" rebar and replaced it with a standard aluminum Bernsten monument stamped, "W.C.M.C. to GLO M.C.," from which I established the following witnesses and reference objects:

4" Balsam	N 43° E	25.15 Feet	
3" Balsam	S 81° E	18.89 Feet	
5" Balsam	N 17° W	21.08 Feet	
6' Steel Sign Post	South	2.00 Feet	
3/4" Iron Pipe	N 87°W	8.97 Feet	(located on water's edge next to wood post)

Signed by

John R. Garske

Date



Surveyor's Michigan License No. 28410
FB # 269, page 65

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1995